


167 Vanforth Street

NDP-REHAB II


STEP WALKER
6393-3R



Loc. 187 Danforth Street
Proj: NDP 2
Block 57E
Issued: Sept. 6, 1971 Expires: October 6, 1971

ROOM 515, CITY HALL
PORTLAND, MAINE 04111
774-4221

Board of Commissioners
PAUL H. FOLEY, Chairman
ROBERT M. BUDD, Vice Chairman
JOHN H. MALCUNIAN
THE REVEREND HAROLD A. McELWAIN
CHARLES W. REDMAN, JR.
THOMAS F. VALLEAU, Executive Director

Mrs. Mary Curran
187 Danforth Street
Portland, Maine

Dear Mrs. Curran:

An examination was made on September 2, 1971 of the premises located at 187 Danforth St, Portland, Maine by Rehabilitation Specialist Max Furrer. Violations of Municipal Codes relating to housing conditions were found as described below.

In accordance with the provisions of the above named codes you are required to correct these defects. Some repairs or improvements will require permits which are obtained from the Building, Health, Fire or other City Departments.

Financial assistance and construction advice are available from the federal government, by contacting the Neighborhood Development Program office at 247 Danforth Street, 774-3611. Please call us to discuss these before beginning work on your property.

Very truly yours,

Joseph E. Furrer, Jr. (per R.C.)
Project Director

BY: *Richard E. Fournier*
Chief, Rehabilitation Services

VIOLATIONS

HOUSING CODE REFERENCE

Exterior:

1. Repair or replace the defective brick and mortar on chimney above roofline.

Interior

1. Determine the reason and remedy the condition that causes the ceiling to show signs of water leakage in living room.
2. Repair or replace the loose ceiling cover in the kitchen.
3. Repair or replace worn floor covering in bath:

3B