Dependable Hood & Duct Cleaning Company, LLC

424 Old Candia Road - Unit 1 Candia, NH 03034 603-483-0199

> www.nhhoodcleaning.com Service@dependablehood.com

Account: Ruski's Tavern

Location: Ruski's Tavern

Loc.Add: 212 Danforth Street

212 Danforth Street Portland, ME 04102

Date: 03/31/2023 **Phone:** (207) 774-7604

Date of Service: 03/30/2023
Frequency: 180 days

Tech Name: Christopher Mailhot - HC-001101 - 1/16/25

Service	Options	Comments
1. Are the filters clean?	Yes	
2. Do any filters need replacement?	No	
3. Is the grease load less than 2000 microns: (Horizontal)	Yes	
4. Is the grease load less than 2000 microns: (Vertical)	N/A	
5. Is the grease load less than 2000 microns: (Hood)	Yes	
6. Is the fan grease load less than 3175 microns?	Yes	
7. Last cleaning/inspection date:	3/30/2023	Dependable Hood and Duct Cleaning Co.
8. Did you clean or inspect the systems?	Cleaned	
Was a Certificate of Performance placed on the hood?	Yes	
10. If a wash system, is the main valve in the open position?	N/A	
11. Are all filters in place?	Yes	
12. Do the fans operate?	Yes	
13. Have the duct dampers been cleaned/inspected?	N/A	
14. Were the exhaust fans cleaned?	Yes	
15. Were the hood grease cups cleaned?	Yes	
16. Does the system appear to be liquid tight?	Yes	
17. Have exhaust fan belts been inspected/are they working?	Yes	Customer performs maintenance of fan motors and belts.
18. Have horizontal ducts been cleaned or inspected?	Yes	
19. Have vertical ducts been cleaned or inspected?	N/A	
20. Are sufficient access panels provided?	Yes	
21. Is there proper signage on access panels?	Yes	
22. Are all areas of the systems accessible?	Yes	
23. Are hoods and exhaust systems free of obstructions?	Yes	
24. Cleaning complies with NFPA '96?	Yes	
25. Type of Cooking systems solid fuel, charbroil or Wok?	Other	Flat Top Grill, Char Grill, Char Broiler, Fryers, Stove Top, Pizza Oven
26. Are the frequencies adequate?	Yes	
27. Are the precipitators/pollution control clean?	N/A	
28. What condition is the rooftop surface in?	Wall Mount Fan	
29. Are there deficiencies in these systems?	No	
30. Are grease containment systems sufficient?	Yes	
31. Are there Type II duct systems?	No	

List deficiencies or comments related:

All systems were cleaned/inspected and a C.O.P was placed on the appropriate hoods.