## CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

	wner/Manag			Inspector Suzanne Hunt		Inspection Date 11/9/2010		
COLE JAMES M JR Locatation CBL			Suzanne Hunt					
LocatationCBL10 GILMAN ST064 E021001			Re-Inspect 14 Days	2	Inspection Type Complaint-Inspection			
	Code	Int/Ext	001 2021001	Floor	Unit No.	Area	Compliance Date	
1)	6-108.(b) Violation: Notes:	Interior Bathroom Interior floors, walls, ceilings and doors Repaired ceiling in bathroom must be painted						
2)	6-113.(d) Violation: Notes:	Interior Kitchen Extension cords. no extension cords can extend thru doorways. Extention cord cannot be used for refrigerator.						
3)	6-113.(c) Violation: Notes:	Interior Various locations Passageways and common stairway. Common areas including basement and hallways must have working lights.						
4)	6-116.(e) Violation: Notes:	Interior Through Out Fire Protection All bedrooms must have hardwired smoke alarms with battery back up. All new smoke alarms must be photoelectric. CO alarms are required just outside of the bedrooms on each level of the dwelling. The CO alarms must also be hardwired with battery back up and interconnected within each unit.						
5)	6-108.(b) Violation: Notes:		s, walls, ceilings an bathroom door mus	Bathroom d doors t be replaced or repaired.				
6) 6-108.(f) Violation Notes:		Interior Kitchen Required equipment and utilities All supplied fixtures must be in working order. The Refrigerator and the stove must be brough into compliance. The thermostat on stove must work, the refrigerator inside temperature must not freeze food.						
Comments:		one hard wired no battery back up smoke detector in bedroom second floor apartment Interconnected hardwired with battery back up smoke and Carbon Mooxide detector required in all units. Unit 2: Stove and Refig need to be in full working order, Door on Bathroom must be replaced. Refrig must be directly plugged into outlet, no Extention cords allowed. Bathroom ceiling stain must be painted. Common areas: All lights through out common area must be working, basement and all corridors, replace light bulbs or repair as necessary. Called Owner at 10:45 a.m. 11/9/10 and Lm regarding spection results. Smh						