



RESTAURANT LOCATION:
**332 St. John Street
 PORTLAND, ME**

PREPARED FOR:
McDonald's USA, LLC
 McDONALD'S PLAZA
 OAK BROOK, ILLINOIS
 60521

SHEET NUMBER:
S-1.1

SHEET TITLE:
PILE LAYOUT PLAN

McDonald's

CONSULTANT:
**DUBOIS
 ENGINEERING
 ASSOCIATES, INC.**
 CONSULTING ENGINEERS, STRUCTURAL, FORENSIC
 117 HARRISON STREET, MANCHESTER, NH 03104
 PH: (603) 666-0900 FAX: (603) 669-0900

Landry
ARCHITECTS

389 Main Street - Salem, NH 03079
 T 603.890.6414 F 603.894.4358

REVISIONS		
NO.	DATE	BY
1		
2		
3		
4		
5		
6		
7		

DRAWN BY: T.E.A.

CHECKED BY: D.A.D.

DATE DRAWN: 06/01/07

DATE ISSUED: 08/14/07

SCALE: AS NOTED

JOB NUMBER: M-1035