

Section 605 – Accessibility

Elements that are altered in Type B dwelling or sleeping units are not required to meet accessibility per Section 605.1 Exception 3.

Section 605.1.1 to Section 605.1.3

Not applicable, there are no alterations to these elements.

Section 605.1.4 - Ramps

Provided a new curb ramp that is more compliant than ICC A117.1 (ramp not required)

Section 605.1.5 to Section 605.1.14

Not applicable, there are no alterations to these elements.

Section 605.2 - Alterations affecting an area containing a primary function

This provision does not apply to installation of new ADA toilets, grab bars at toilets, removable shower seats, and wall hung sinks to Type B unit bathrooms per Exception 4. (voluntary addition to accessibility)

Section 606 Structural

N.A., no alteration to these elements

Section 607 – Energy Conservation

N.A.

1.0.C Interior Finish System:

NFPA 101 - 2009:

Classification of Occupancy: Chapter 43, “Building Rehabilitation” Section 43.4 “Renovations”

NFPA 101 – Chapter 43, Section 14.3.3 and Chapter 10, Section 10.2

Wall and Ceiling Finishes:

	NFPA	
Exit Enclosures and Passageways	Class A	Not Applicable
Corridors	Class A or B	Not Applicable
Rooms and Enclosed Spaces	Class A,B or C C on low partitions	Not Applicable

Interior Floor Finishes:

Vertical Exits / Exit Corridors	Class I or II	Not Applicable
Rooms and Enclosed Spaces	NA	provided

End of Code Compliance Report