## Existing 1st Floor

## Proposed Changes

Interior Renovations


Remove interior partitions Install new 2 ply LVL 1  $3/4 \times 10$ " Support Beams-

Rebuild Existing Exterior Malls, as Required, with

new 2x6
Build Out Remaining Exterior Mall to 2x6 Depth as

Required
New R21 Mall Insulation

1/2" Plywood Sheathing 1/2" Drywall Interior finish Clad Board siding



LIVING AREA