## University of Southern Maine Luther Bonney Building Fire Alarm System Replacement Portland, ME

## Comments:

☐ 1 - Reviewed, No Exception Taken	
x 2 - Reviewed, Revise as Noted	MADDO
3 - Revise and Resubmit	WBRC
4 - Rejected	ARCHITECTS · ENGINEERS
5 - Other, Held for Record, Not Reviewed	
	sign concept and the information given
in the Contract Documents. Corrections or comments m review do not relieve the Contractor from compliance wil Documents and applicable laws, codes and regulations. include review of an assembly of which the item is a con responsible for: dimensions to be confirmed and correlat pertains solely to the fabrication; processes, means, me procedures of construction; coordination of the Work wit Work in a safe and satisfactory manner.	ade on the shop drawings during this the requirements of the Contract Review of a specific item shall not nponent. The Contractor is ted at the jobsite; information that thods, techniques, sequences and

Notification devices submitted as red. Provide white devices as specified.

**Prepared For:** 

TRT Electric 65 Washington Street Augusta, ME 04330

**Presented By:** 



BK Systems, Inc. 4 Cote Avenue Goffstown, NH 03045 Telephone: (603) 647-8775

Fax: (603) 647-4806

**Ricky Houde**