


THIS IS NOT A BOUNDARY SURVEY

### Mortgage Loan Inspection (SKETCH)

**NOTE:**

1.) **THIS IS NOT A BOUNDARY SURVEY** accordingly, no professional opinion is made as to whether the lines shown hereon are the true boundary lines. This sketch is prepared solely for the mortgagee specified below and its title insurer for the sole purpose of determining whether the principal structure(s) meet requirements set forth below. **THE PREPARER IS NOT LIABLE FOR ANY OTHER USE BY ANY OTHER PERSON OR ENTITY.** Please refer to the attached terms and conditions.  
2.) The MLI terms and conditions are an integral part of this MLI sketch and shall be reviewed in conjunction with this sketch.



This plan has been prepared from an inspection of the site on 09/13/2013  
The Principal Structure(s) depicted DID conform with municipal setback requirements of local zoning at time of construction.  
The principal structure(s) IS NOT located in a FEMA 100 year special flood hazard area.  
Source Deed Provided: 26317/124 Plan Vol. \_\_\_\_\_ Back \_\_\_\_\_ Page \_\_\_\_\_

PREPARED FOR:  
**CORNERSTONE TITLE & SETTLEMENT COMPANY**

BUYER: **GILLIAN K. CRIDLER & JOSHUA A. CRIDLER**  
SELLER: **JAMES R. SABATINO & MICHAEL RECO**  
LOCATION: **139 LONGFELLOW STREET PORTLAND, ME**  
TAX MAP REFERENCE: **MAP 119 LOT B-4**

SCALE: 1" = 30'  
DATE: 09/16/13

REQD. BY: **CORNERSTONE TITLE & SETTLEMENT COMPANY**  
DRAFTED BY: **JODY**  
JOB NO. 13-527B



Prepared By:  
**SurveyWorks, Inc.**  
Land Use Consultants  
528 RIVER ROAD  
Cresco, Maine 04236  
Tel. (207) 948-4480