October 30, 2017

ZINN PETER W 187 FORESIDE RD FALMOUTH, ME 04105

CBL: 123 C003001

Certified Mail 7014 1820 0001 4049 7017

Located at: 315 WOODFORD ST

Dear ZINN PETER W,

An evaluation of the above-referenced property on 10/30/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 12/01/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely.

Jason Duval

Code Enforcement Officer

## CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager ZINN PETER W		Inspector Jason Duval	Inspection Date 10/30/2017
315 WOODFORD ST	123 C003001	Failed	Housing Safety Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

CO alarm required in top floor of dwelling.

Comments: Missing CO alarm in top floor. Contact Housing Safety at housingsafety@portlandmaine.gov or 207-

756-8131 to schedule a re-inspection.