

Inspection and Testing Certificate

Presented To

Plymouth Court Apartments

244-246 WOODFORD ST.

PORTLAND ME 04103

USA

This site has been inspected and tested in compliance with applicable standards.

Completed

Wednesday, November 04, 2015

Test Session: 11/04/15

ACCEPTED BY

Neils Knudsen

Plymouth Court Apartments

244 WOODFORD ST

PORTLAND ME 04103

USA

TESTED BY

Mike Todd and Marc Elliott

Norris Inc

2257 Broadway

South Portland ME 4106

USA

Norris Inc



PO Box 2551
2257 West Broadway
South Portland, ME 04106

1.800.370.3473
fax 207.879.0540

Inspection Summary

Building Information

PROPERTY	Plymouth Court Apartments	CONTACT	Neils Knudsen
ADDRESS	244-246 WOODFORD ST.	PHONE	
CITY/STATE/ZIP	PORTLAND, ME 04103	MOBILE	
COUNTRY	USA	EMAIL	

Inspector Information

COMPANY	Norris Inc	CONTACT	Technician 3
ADDRESS	2257 Broadway	PHONE	(800) 370-3473
CITY/STATE/ZIP	South Portland, ME 4106	MOBILE	
COUNTRY	USA	EMAIL	tech3@norrisinc.com

NAME	INITIALS	QUALIFICATION AND PROFICIENCIES
Technician 3	T3	

Testing Summary

EQUIPMENT TYPE	TOTAL	TESTED	PASSED	FAILED
Fire Control Panel	2	2(100 %)	2(100 %)	0(0 %)
Initiating Device	16	16(100 %)	8(50 %)	8(50 %)
Alarm Notification Appliance	8	8(100 %)	8(100 %)	0(0 %)
Supervising Station Transmitting Equipment	1	1(100 %)	1(100 %)	0(0 %)

Certification

The equipment specified herein was inspected and tested according to the NFPA 72 standard for fire alarm and signaling systems, with the inspection completed on Wednesday, November 04, 2015

ACCEPTED BY

11/11/2015
Neils Knudsen
Building Representative

TESTED BY



11/11/2015
Mike Todd and Marc Elliott
Technician

System Details

Control Units

MANUFACTURER	FCI	DESCRIPTION	Basement 246 side
MODEL	FC-72	S/W VERSION	
SERIAL NUMBER		LAST UPDATE	
INSTALL DATE	11/3/2015	S/W LOCATION	

Monitoring Information

Basement 246 side by FACP			
TYPE	Digital Alarm Communicator Transmitter	INSTALL DATE	11/3/2015
MANUFACTURER	Radionics	TEST START	11/4/2015
MODEL	D7212	TEST COMPLETE	11/4/2015
SERIAL NUMBER		Time to Transmit to Supervising Station	
MONITORING ORGANIZATION	Protection One	ALARM SIGNAL	0 sec
MONITORING ORGANIZATION PHONE		ALARM RESTORE	0 sec
MONITORING ORGANIZATION EMAIL		TROUBLE SIGNAL	0 sec
MONITORING ORGANIZATION ACCOUNT NUMBER	P098-2284	TROUBLE RESTORE	0 sec
MONITORING PHONE LINE 1		SUPERVISORY SIGNAL	0 sec
MONITORING PHONE LINE 2		SUPERVISORY RESTORE	0 sec
MONITORING RETRANSMISSION ENTITY			

Open Corrective Action & Solution Summary

The following 8 corrective action(s) remain open following the system inspection, testing or maintenance activities

EQUIPMENT TYPE	ADDRESS	DESCRIPTION
Smoke Detector - General		Basement 246 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	
Smoke Detector - General		Basement 244 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	
Smoke Detector - General		1st Fl 246 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	
Smoke Detector - General		1st Fl 244 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	
Smoke Detector - General		2nd Fl 246 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	
Smoke Detector - General		2nd Fl 244 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	
Smoke Detector - General		3rd Fl 246 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	
Smoke Detector - General		3rd Fl 244 Side
	Created By:	Technician 3
	Creation Date:	11/11/2015
	Corrective Action:	No power supervision
	Proposed Solution:	

EQUIPMENT TYPE

ADDRESS

DESCRIPTION

Testing Details

Fire Control Panel

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Fire Alarm Panel		Basement 246 side	Manual	11/4/2015 4:00 PM
		Manufacturer	FCI	
		Model	FC-72	
		Serial Number		
		Visual Inspection	True	
		Functional Inspection	True	
		Alarm Signal	0 sec	
		Trouble Signal	0 sec	
		Supervisory Signal	0 sec	
		Alarm Verification Timer (s)	30 seconds	
Fire Panel Batteries		FACP (2 - 12v7ah)	Manual	11/4/2015 4:00 PM
	Comment:	replaced while at site after failing load test		
		Visual Inspection	True	
		Functional Inspection	True	

Initiating Device

Failed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Smoke Detector - General		Basement 246 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General		Basement 244 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General		1st FI 246 Side	Manual	11/11/2015 3:53 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General		1st FI 244 Side	Manual	11/11/2015 3:54 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General		2nd FI 246 Side	Manual	11/11/2015 3:54 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General		2nd FI 244 Side	Manual	11/11/2015 3:54 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General		3rd FI 246 Side	Manual	11/11/2015 3:55 PM
		Visual Inspection	True	
		Functional Inspection	True	
Smoke Detector - General		3rd FI 244 Side	Manual	11/11/2015 3:55 PM
		Visual Inspection	True	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	True	

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Manual Fire Box		Basement 246 Side	Manual	11/11/2015 3:49 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Fire Box		Basement 244 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Fire Box		1st FI 246 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Fire Box		1st FI 244 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Fire Box		2nd FI 246 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Fire Box		2nd FI 244 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Fire Box		3rd FI 246 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	
		Functional Inspection	True	
Manual Fire Box		3rd FI 244 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	
		Functional Inspection	True	

Alarm Notification Appliance

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		Basement 246 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Audible And Visible		Basement 244 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Audible And Visible		1st FI 246 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Audible And Visible		1st FI 244 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Audible And Visible		2nd FI 246 Side	Manual	11/11/2015 3:50 PM
		Visual Inspection	True	
		Functional Inspection	True	
Audible And Visible		2nd FI 244 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	True	
Audible And Visible		3rd FI 246 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	
		Functional Inspection	True	
Audible And Visible		3rd FI 244 Side	Manual	11/11/2015 3:51 PM
		Visual Inspection	True	
		Functional Inspection	True	

Supervising Station Transmitting Equipment

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Digital Alarm Communicator Transmitter		Basement 246 side by FACP	Manual	11/4/2015 4:00 PM
	Comment:	Replaced 7ah battery that failed load test at request of customer		
		Manufacturer	Radionics	
		Model	D7212	
		Serial Number		
		Visual Inspection	True	
		Functional Inspection	True	
		Alarm Signal	0 sec	
		Alarm Restore	0 sec	
		Trouble Signal	0 sec	
		Trouble Restore	0 sec	
		Supervisory Signal	0 sec	
		Supervisory Restore	0 sec	

Device/Equipment Details

Fire Control Panel

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Fire Alarm Panel					
	Basement 246 side	FCI	FC-72		11/3/2015
Fire Panel Batteries					
	FACP (2 - 12v7ah)				11/3/2015

Initiating Device

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Manual Fire Box					
	Basement 246 Side				12/31/2011
	Basement 244 Side				12/31/2011
	1st FI 246 Side				12/31/2011
	1st FI 244 Side				12/31/2011
	2nd FI 246 Side				12/31/2011
	2nd FI 244 Side				12/31/2011
	3rd FI 246 Side				12/31/2011
	3rd FI 244 Side				12/31/2011
Smoke Detector - General					
	Basement 246 Side				12/31/2011
	Basement 244 Side				12/31/2011
	1st FI 246 Side				12/31/2011
	1st FI 244 Side				12/31/2011
	2nd FI 246 Side				12/31/2011
	2nd FI 244 Side				12/31/2011
	3rd FI 246 Side				12/31/2011
	3rd FI 244 Side				12/31/2011

Alarm Notification Appliance

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Audible And Visible					
	Basement 246 Side				12/31/2011
	Basement 244 Side				12/31/2011
	1st FI 246 Side				12/31/2011
	1st FI 244 Side				12/31/2011
	2nd FI 246 Side				12/31/2011
	2nd FI 244 Side				12/31/2011
	3rd FI 246 Side				12/31/2011
	3rd FI 244 Side				12/31/2011

Supervising Station Transmitting Equipment

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Digital Alarm Communicator Transmitter					
	Basement 246 side by FACP	Radionics	D7212		11/3/2015