


System Inputs	System Outputs		
	Control Unit Annunciation	Notification	Safety Control
Protection 1 Branch 11660			
10 Manual Drive, Portland, ME 04103 PH# 1-800-310-5011			
			
System Pull Stations	X		
System Smoke Detectors	X		
System Heat Detectors	X		
Sprinkler Water Flow	X		
Sprinkler Gate Valve Tamper			
Sprinkler Air Pressure			
FACP AC Loss	X		
FACP Low Battery	X		
FACP Ground Fault	X		
Phone Line #1 Fail	X		
Phone Line #2 Fail	X		
Actuate common alarm signal indicator	X		
Actuate audible alarm system	X		
Actuate common supervisory signal indicator	X		
Actuate audible supervisory signal	X		
Actuate common trouble signal indicator	X		
Actuate Basement floor evacuation signals	X		
Actuate 1st Floor Evacuation Signals	X		
Actuate 2nd Floor Evacuation Signal	X		
Actuate 3rd Floor Evacuation Signals	X		
Actuate 4th Floor Evacuation Signals	X		
Actuate 5th Floor Evacuation Signals	X		
Transmit fire alarm signal to supervising station	X		
Transmit supervisory signal to supervising station	X		
Transmit trouble signal to supervising station	X		
Evergreen Cemetery			
672 Stevens Ave			