

Field Report

The Park Danforth

Portland ME

Project No: 13-059-00

Field Report No: 1

To: Mark Donovan
 PC Construction
 131 Presumpscot Street
 Portland ME

Time of Visit: 12:00 PM
Date of Visit: 11/10/2015
Weather: P Sunny, Cool

Submitted by: Scott Timmons

Copies:

Present: Scott Timmons (LBA)

- Ron Norton Construction Management Consultir
- Mark Donovan PC Construction
- Andrew Pires PC Construction
- Kemp Carey PC Construction
- Bob Metcalf Mitchell & Assoc
- Dan Burne Becker Structural
- Ian MacDonald Allied Engineering
- Stephen Markiewicz Allied Engineering
- Susan Hathaway Allied Engineering

Item	Description	Status:
------	-------------	---------

- | | | |
|---|---|-------------|
| 1 | <p><u>WORK IN PROGRESS</u></p> <ul style="list-style-type: none"> a. CIP concrete footing placement along H-Line, and 11.2 Line, from G to H Line. b. CIP foundation wall formwork along 11.2 Line from G to H Line. c. Electrical ductbank piping from Main Electrical Room G013 - towards existing drive. d. Footing formwork and reinforcing steel along E-Line, from 11-Line up to approx 7.5 Line e. Footing formwork for Forest Ave terrace with reinforcing steel placement ongoing. | Observation |
|---|---|-------------|

Attached Sketches:



Foundation wall formwork @ 11.2-Line from G to H-Line. H-Line footings visible in the background.

A



Tower construction site (from Arbor Street looking south)

B



CIP footing placement along H-Line. Wall formwork along 11.2-Line visible in background

A



Forest Ave terrace footings

B



Electrical ductbank at Main Electrical Room G013

A



View from existing service drive looking north - northwest

B