



BOLTS, NOTE 1: (2) 2x12s PLUS 1/8" PLYWOOD BOTH SIDES OF BEAM BEARING ON BOTTOM FLANGE AND FASTENED WITH (2) 1/2"  $\phi$  A307 THRU BOLTS IN 9/16"  $\phi$  HOLES @ 3' O.C. (TYP.).

13 FERNALD TERRACE  
PORTLAND, ME

SECTION  
1/2" = 1"



7.26.17