

Permitting and Inspections Department Michael A. Russell, MS, Director

March 5, 2018

INGRAHAM DAVID A B & 9 BROOKSIDE TER VEAZIE, ME 04401

CBL: 172 G007001 Located at: 9 RAY ST Certified Mail 7015 0920 0001 0776 6355

Dear INGRAHAM DAVID A B &,

An evaluation of the above-referenced property on 03/02/2018 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 04/03/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Jason Duval

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager INGRAHAM DAVID A B &		Inspector Jason Duv		Inspection Date 3/2/2018
Location	CBL	Status		Inspection Type
9 RAY ST	172 G00	7001 Failed		Inspection
Code	Int/Ext	Floor Unit No.	Area	Compliance Date
1) 55.05	Interior			
Violation:	NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.			
Notes:	Hard wired Co alarms required for basement, Unit 1, and Unit 3.			
2) 55.051	Interior			
Violation	NEPA 101, 7.2.1.8.1 DOORS SHALL BE SELE-CLOSING & SELE-LATCHING: A door leaf normally			

Violation:

NFPA 101- 7.2.1.8.1 DOORS SHALL BE SELF-CLOSING & SELF-LATCHING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing

or automatic-closing in accordance with 7.2.1.8.2, unless otherwise specified by 7.2.1.8.3.

Notes:

Fire doors are required to self close and self latch.

Comments:

Field Inspection 3/2/18- Co alarm required for basement, unit 1, and unit 3. Fire doors are required to self close and self latch.