CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

June 6, 2017

Responsible Party 1:				
STREET TRACY				
188 BOLTON ST				
PORTLAND, ME 04102				
Location	CBL	Inspection Date		
Location 188 BOLTON ST	CBL 186A D016001	Inspection Date 5/19/2017		
		=		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 6/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 80- ANNEX D.4 1-HOUR FIRE DOORS ASSEMBLIES REQ; Listings are provided for floor fire door assemblies that are installed in fire-rated floor-ceiling or roof-ceiling assemblies that have been tested in accordance with the methods described in NFPA 288. The listing indicates the fire-rated assembly and the hourly rating (3 hours, 2 hours, 1.5 hours, 1 hour, .75 hours) for which the door can be permitted to be used so that access to the space above the ceiling or to the floor above can be provided without adversely affecting the fire resistance rating of the entire assembly. The listing provides limitations on the maximum size of an individual door opening and the total area of all door openings permitted for each 100 square feet of floor or ceiling. All doors to units need to be fire rated and self closing. Door to garage is fire rated but not labled as such.	
CITY OF PORTLAND RULES AND REGS- CHAPTER 4.6 LABEL UNIT DOORS; 4.6 Commercial suites shall be designated as approved by the FD. In single floor buildings letter designations shall be acceptable. 4.6.1 Residential units shall be designated using numericals. 4.6.2 The first numerical of each residential unit shall be the floor designation. 4.6.3 In single floor buildings the floor designation shall be omitted.	
NFPA 101- 7.2.2.4.2 HANDRAILS ARE NOT CONTINOUS; Required guards and hardrails shall continue for the full length of each flight of stairs. At turns of new stairs, inside handrails shall be continuous between flights at landings. No returns on handrails in common stairwells	

Violation		Proposed Date of Completion
31.3.2.1.1 shall be protected	R PROTECTION REQUIRED; The areas described in Table as indicated: Boiler and fuel-fired heater rooms serving more inimum separation/protection is 1 hour or sprinklers) ment need to be sprinklered	
FINAL DATE OF COMPLET	ED VIOLATION(S)	//
FIRE PREVENTION BUREA	U RE-INSPECTION OF COMPLETED VIOLATION(S)	//
-	tht to reject or modify any proposed plan of action, and may unical capacity to complete the proposed plan. Please contact ATION	-
understand that I must con	tions listed within the timeframes provided. If I require add tact the Fire Prevention Bureau <u>prior to the deadline</u> to requ u's discretion to grant or deny.	- ·
	t is my responsibility to schedule a reinspection of my prope to. My failure to schedule a reinspection shall be deemed ar medied.	
	agreement, I understand that I am liable for penalties pursuces §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	