Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Anne M. Torregrossa Associate Counsel

Michael I. Goldman Associate Counsel

July 14, 2016

NOTICE OF INTENT TO PROSECUTE

Ibourk M. Moulay 28 Codman Street

Portland, Maine 04103

Bradley Street Condominium Association 1363 Congress Street

Portland, Maine 04101

TTRJ, LLC P.O. Box 2156 Windham, Maine 04062

TTJR, LLC and **Bradley Street Condominium Association**

c/o Alan E. Wolf P.O. Box 1292

Portland, Maine 04104

1363 Congress Street RE:

> CBL188 C001001 CBL188 C001001 CBL188 C001001

To Whom it May Concern,

Please see the attached Inspection Violations. The City of Portland Fire Department has referred this matter to me for prosecution. In order to avoid prosecution, you must submit to Fire Prevention Bureau a plan of action to remedy the violations no later than July 29, 2016.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION WITHIN THE TIMEFRAME PROVIDED WILL RESULT IN LEGAL ACTION AND THE IMPOSITION OF CIVIL PENALTIES.

Please feel free to contact Tori Ross of the Fire Prevention Bureau at (207)874-8400 with any questions. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Anne M. Torregrossa Associate Counsel Michael I. Goldman Associate Counsel

Sincerely,

Anne M. Torregrossa

Associate Corporation Counsel

City of Portland

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

380 Congress Street Portland, Maine 04101

#353900

Inspection Violations

Owner/Manager IBOURK MOULAY M		Inspector Scott Corey	Inspection Date 6/21/2016
1363 CONGRESS ST	188 C001001	Failed	Fire Company-FP Routine Inspec

Code Int/Ext Floor Unit No. Area Compliance Date

1) 80.56

Violation: NFPA 101- 7.2.8.5.1 HANDRAILS REQUIRED ON STAIRS; ALL FIRE ESCAPE STAIRS SHALL

HAVE WALLS OR GUARDS AND HANDRAILS ON BOTH SIDES IN ACCORDANCE WITH 7.2.8.4.1

(B).

Notes: BROKEN RAILS FRONT AND REAR STAIRCASE

2) 55.20

Violation: NFPA 101- 31.3.3.2 INTERIOR FINISH; INTERIOR WALL AND CEILING FINISH MATERIALS

COMPLYING WITH 10.2 SHALL BE PERMITTED AS FOLLOWS:

(1) EXIT ENCLOSURES- CLASS A OR B

(2) LOBBIES AND CORRIDORS- CLASS A OR B

(3) OTHER SPACES- CLASS A, B, OR C.

Notes: HOLES IN WALLS FRONT AND REAR STAIRCASE

3) 3.011

Violation: NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; THE AREAS DESCRIBED IN TABLE

31.3.2.1.1 SHALL BE PROTECTED AS INDICATED:

BOILER AND FUEL-FIRED HEATER ROOMS SERVING MORE THAN A SINGLE DWELLING UNIT

(MINIMUM SEPARATION/PROTECTION IS 1 HOUR OR SPRINKLERS)

Notes: BOILER FOR 3RD FLOOR NEEDS PROTECTION

Comments: