From:	David Margolis-Pineo
То:	Tom Errico
CC:	Barbara Barhydt; Helen Donaldson; Jean Fraser
Date:	5/6/2015 1:44 PM
Subject:	Sidewalk material Policy

Bishop St is asphalt.

1242 Congress St is concrete. It appears in good condition (Google earth) We will not require concrete unless more than 50% is disturbed.