

## **SECTION 01400 - QUALITY CONTROL**

---

### PART 1 - GENERAL

#### 1.1 CONSTRUCTION LAYOUT

- A. The Contractor shall take the responsibility for verifying and locating existing systems and laying out his work in three dimensions in accordance with the drawings and with great accuracy in establishing and maintaining dimensional control so that it will agree with established lines and levels. All changes from the plans issued for permit shall be noted on the permit set. The permit set shall be turned over to the Architect after completion. Final retainage will not be released without the "As Built" permit submittal.
- B. Any discrepancy between drawings and existing conditions shall be brought to the attention of the Architect immediately describing such discrepancies. Work shall not proceed until he has received written instructions. The Contractor and Architect shall follow-up such communications in writing.

#### 1.2 TESTS AND INSPECTIONS

- A. The Contractor shall coordinate with the testing agency hired by the Owner making the tests and inspections of workmanship and materials as may be required by the Building Code, State and municipal laws, and as required under the various sections of the specifications.

PART 2 - PRODUCTS (Not applicable)

PART 3 - EXECUTION (Not applicable)

**END OF SECTION 01400**