

4/15/02 - checked set boxes - OK checked sonar
tube depth 4' + - OK to continue. Tom M

5/12/03 needs go rail/handrail system left
side going ~~the~~ up. She will call when
completed. AR

6/7/03 Handrail system left of Lurline
also for intermediate steps & NO Return
He will want the 34"-36" extensions w/return
Contractor left detailed memo. (P)

6/12/03 Owner asked HR to call her (P)

6/23/03 completed. A Nowe