	R802.4(2))			
		,		
(Pitch, Span, Spacing & Dimension (Table R802, St(1) - R 802.5.1(8)) R96f Rafter; Framing & Connections (Section R802, 3 & R802.3.1)	JB		
de	Sheathing; Floor, Wall and roof (Table RS03.2.1.1(1)	44 Floor - SpRoof - Walks	5 2 7/16" 0.5B	
)	Fastener Schedule (Table R602.3(1) & (2))			ļ
	Private Garage			
(Living Space? Beside			
F	(Above or begide)	11 to 11/2 / 12/2	1 /8 fire rated on	
T.	Onemino Protection (Section B309.2)		meson of the line of the	
E CO		door !	Steel Fire Ruted - 40 minute	,
(Emergency Escape and Rescue Openings (Section R310)	016-dar-		
	Roof Covering (Chapter 9)	Asphalt?	3 Tab Asphalt	
35.5	Safety Glazing (Section R308)	weed whin 2 of a	dor S Tenperal on Hankers ment	4
ACC SON	Attic Access (Section R807)	Not shown	Through Below Closet	Jose J
) {	Chimney Clearances/Fire Blocking (Chap. 10)	NA	P	
at a	Header Schednle (Section 502.5(1) & (2)	Not shown	3-2×8 ~/ ply hetween	
)	Energy Efficiency (N1101.2.1) R-Factors of Walls, Floors, Ceilings, Building Envelope, U-	R-30 Clost / Clng		
•		9.19 walls 0		

FACOU FUNCTIONALUB	**************************************		SAT
Type of Heating System			, .
Means of Egress (See R311 & R312)	Total *	Ster Detail	0 03
Basement		, <i>j</i> , 11 -	•
Number of Stairways		railing 214 clover	
Interior /	35.	hand rail	TT DMP
Exterior 3	10 t	4" Max. Specing	INEIN
Treads and Risers		14-71/2 6:58	0. 20.
Width (Section R3115.1)	2012 15 * Hitter St. 24:15	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ON6&2
Headroom (Section R311.5.2)	- Same as	- Same as above specs	014 1 144
	- Graball	- governi is 36" 1/2 wall -dymall -	•
(Section-RG12 & R311.5.6 - R311.5.6.3)			
Smoke Detectors (Section R313)	New bean	New bedroom interconnected	ا ان
Location and type/interconnected			
Dwelling Unit Separation (Section R317) and IBC - 2003 (Section 1207)			
Deck Construction (Section R502.2.1)	New Letails on 16" on ledye	7-1/2"X5" lay 60/t5 exery 16" on ledger / hongers on 70,75t5	PAG
	all ledgers - Jim		JE 4/4


Permit Nbr 05-1490	Location of	f Construction 1	1 PIERCE AVE		Appl. D
Status Hold		Permit Type A	dditions - Dwellings		Issue D
CBL 250 A018	3001	District Nbr 3	Estimated Cost	\$71,000.00	Date Clo
					anakin padi makamanakina
Comment Date	Comment				
10/21/200	faxed review s	heets to builder and	called and went over		
	Name tmm		Follow Up Date		Comple
	P				satuti lohdud ke tu satu
to the control of the					
er en					

City of Portland INSPECTION SERVICES

Room315 389 Congress Street Portland, Maine 04101

Telephone: 207-874-8703 or 207-874-8693

Facsimile: 207-874-8716



FACSIMILE TRANSMISSION COVER SHEET

TO: Jeff	FROM: Tammy Munson
FAXNUMBER: <u>199-3292</u>	, , ,
TELEPHONE:	RE: 11 Pierce
DATE: 10/21/05	
Comments: Please call u	/ guestions - 874-8706
fax reply - 874	
	<i>y</i>

Table	Secon Dime	First Dime (Tabl	Built- Dime Sill/B	Girde	Anch. Lally	Venti Craw	Found (Section	STI Footin (Table (Section)	Soil ty	_
Attion and distinct Floor Total Capacita	Second Floor Joist Species Dimensions and Spacing (Table R502.3.1(1) & Table R502.3.1(2))	First Floor Joist Species Dimensions and Spacing (Table R502.3.1(1) & Table R502.3.1(2))	Built-Up Wood Center Girder Dimension/Type Sill/Band Joist Type & Dimensions	Girder & Header Spans (Table R 502.5(2))	Anchor Bolts/Straps, spacing (Section R403.1.6) Lally Column Type (Section R407)	Ventilation/Access (Section R408.1 & R408.3) Crawls Space ONLY	Foundation Drainage, Fabric, Damp proofing (Section R405 & R406)	STRUCTURAL Footing Dimensions/Depth (Table R403.1 & R403.1(1), (Section R403.1 & R403.1.4.1)	oad Value (Table R40 onent	ONE AND TWO FAMILY
	NA	2x10'5 16"00 -	N/A 2×6 Drsice	OK	Coci Mice.	, ,	NA	OK-4 first	Submi	PLAN REVIEW
		~							Findings/Revisions/Dates	CHECKLIST

\

	<u>(</u>	Ma,	(F)	(SE)	
Energy Efficiency (N1101.2.1) R-Factors of Walls, Floors, Ceilings, Building Envelope, U-	Chimney Clearances/Fire Blocking (Chap. 10) Header Schedule (Section 502.5(1) & (2)	Safety Glazing (Section R308) Attic Access (Section R807)	Emergency Escape and Rescue Openings (Section R310) Roof Covering (Chapter 9)	(Section R309) Living Space? (Above or beside) Fire separation (Section R309.2) Opening Protection (Section R309.1)	Pitch, Span, Spacing& Dimension (Table R802.5.1(1) - R 802.5.1(8)) Roof Rafter; Framing & Connections (Section R802.3 & R802.3.1) Sheathing; Floor, Wall and roof (Table R503.2.1.1(1)
Carl	Not shows	Neck whin 2' of doors	Asphalt?	L'e to ridge letter?	Oll H4 Floor - 5/8 Root - Walls ?

	3			}		<u> </u>)						
	Deck Construction (Section R502.2.1)	Dwelling Unit Separation (Section ⊆17) 600 IBC – 2003 (Section 1207)	Smoke Detectors (Section R313) Location and type/Interconnected	Guardrails and Handrails (Section R312 & R311.5.6 - R311.5.6.3)	Headroom (Section R311.5.2)	Width (Section R311.5.1)	Treads and Risers (Section R311.5.3)	Exterior 3	Interior /	Number of Stairways	Basement ()/1	Type of Heating System	Factor Fenestration
deck & addition	Mid details on		Not Shown				J. ta. 1						
2													

This page contains a detailed description of the Parcel ID you selected. Press the **New Search** button at the bottom of the screen to submit a new query.

Current Owner Information

Card Number 2 of 1
Parcel ID 250 ADLAGGL
Location L1 PIERCE AVE
Land Use SINGLE FANILY

Owner Address BARTLETT CAROL A 8 RICHARD K JTS

PORTLAND ME 04102

Book/Page

Legal 250-A-18

PIERCE AVE 11

28000 **SF**

Current Assessed Valuation For Fiscal Year 2006

Land Building Total \$57,480 \$85,330 \$142,810

Estimated Assessed Valuation For Fiscal Year 2007*

Land Building Total \$75,900 \$100,200 \$176,100

Property Information

Year Built 1957	Style Cape	Story Height I	sq. Pt. 1225	Total Acres 0.643	
Bedrooms 2	Pull Baths	Half Baths	Total Rooms	Attic Full Fin./w h	Basement Full
Outbuildings					
Type	Quantity	Year Built	Size	Grade	Condition
SHED-FRANE	l.	1989	8X16	С	A
SHED-FRAME	I	1960	PX50	С	P

Sales Information

Date Type Price Book/Page

Picture and Sketch


Picture Sketch Tax Map

Click here to view Tax Roll Information.

Any information concerning tax payments should be directed to the Treasury office at 874-8490 or e-

Value subject to change based upon review of property status as of 4/1/06. The tax rate will be determined by City Council in May 2006.





<u>Descriptor/Area</u>

- A:FA/1Fr/B 780 sqft
- B:WD 288 sqft
- C:FBAY 16 sqft



424 Fore St., Portland, ME 04101 Phone 207.842.2800 Fax 207.842.2828

October 11, 2005

Mr. Jeff Bartlett Ultra House, Inc. PO Box **2148** South Portland, ME **04116-2148**

Re: CONTRACT FOR ENGINEERING SERVICES

Bartlett Residence Renovation

Structural Analysis

Project Number: 5070

Dear Jeff:

Thank you for the opportunity to provide you with structural engineering services for the Bartlett residence at 11 Pierce Avenue in Portland, ME. Based on our conversation, I understand that this is an addition between the existing house and existing garage.

Casco Bay Engineering's scope of services was limited to design for the roof of the proposed connector addition including design of roof rafters and roof beams. We have provided hand drawn markups of beam and rafter sizes on the roof framing plan provided to us. Please refer to this drawing **for** the appropriate beam and rafter sizes. We have not analyzed lateral loads or any other portion of the building including the existing house or garage structure. No other services were provided by Casco Bay Engineering.

To the maximum extent permitted by the law, the Client agrees to limit the liability of Casco Bay Engineering for any and all claims, losses, costs, damages of any nature whatsoever or claims expenses from any cause or causes to the total fee for services paid to Casco Bay Engineering. Such claims and causes shall include, but are not limited to negligence, professional errors or omissions, strict liability, breach of contract warranty.

Thank you.

Sincerely,

Eric Dube, President Casco Bay Engineering



424 Fore St., Portland, ME 04101 Phone 207.842.2800 Fax 207.842.2828

October 11,2005

Mr. Michael Nugent Inspection Services Manager City of Portland 389 Congress Street Portland, ME **04101**

Re: Bartlett Residence, 11 Pierce Ave., PORTLAND

Project Number: 5070

Dear Mr. Nugent:

This letter is to confirm that we have designed the roof framing (including roof rafters and beams) for the garage to house connector addition in accordance with the 2003 International Building Code, Structural loads chapter, for the appropriate residential loading.

Please contact us if you have any additional questions or concerns.

Sincerely,

Eric Dube President

Casco Bay Engineering

Carolyn C. Bird, P.E.

Vice President

Casco Bay Engineering