

REPORT OF PRE-CONCRETE REINFORCING STEEL INSPECTION

CLIENT:	Old Dominion Freight Lines 500 Old Dominion Way Thomasville, NC. 27360 Attn: Philip Danner		PROJECT:	Old Dominion Building Expansion 185 Rand Road Portland, ME			
DATE:	August 25, 2	014	REPORT #:	14-55-000			
		nforcing Steel for location the approved set of dra					orcing
Location:	Wall: From 1	10-15, over to bulkhead	@ Northwest corner				
Proper Siz	ze:	Yes No	Anchor B	olts Placed:	Yes	No	N/A
Proper Gi	rade:	Yes No	Proper Sp	oacing:	Yes	No	
Proper Qu	uantity:	Yes No	Proper C	learance:	Yes	No	
Masonry/	Wall Dowels:	Yes (No) N/A	A Proper La	ap Splice:	Yes	No	N/A
Embeds P	laced:	Yes No N/A	A Area of P & clear of	lacement fre f debris:	ee Yes	No	
Drawing l	Detail: <u>1 S3</u>	.1, 2 S3.1					
Shop Drav	wing Detail:	<u>S1.1</u>					
*Remarks	s: <u>Bar</u>	was set into existing wal	l using epoxy				
Inspec	Kraytenberg tor/Technician Yurner Consult						
☐ Non Com	oliant ✓ Compliant		✓ Ren	✓ Remarks		☐ Fix	