



## REPORT OF PRE-CONCRETE REINFORCING STEEL INSPECTION

<b>CLIENT:</b> Old Dominion Freight Lines 500 Old Dominion Way Thomasville, NC. 27360 Attn: Philip Danner	<b>PROJECT:</b> Old Dominion Building Expansion 185 Rand Road Portland, ME
<b>DATE:</b> August 28, 2014	<b>REPORT #:</b> 14-55-00014-010A

On site to inspect the Reinforcing Steel for locations listed below. Unless noted otherwise, all reinforcing steel is in accordance with the approved set of drawings, specifications and applicable codes.

**Location:** Walls: Between Line A & A.5, 16-10

Proper Size:	(Yes)	No		Anchor Bolts Placed:	(Yes)	No	N/A
Proper Grade:	(Yes)	No		Proper Spacing:	(Yes)	No	
Proper Quantity:	(Yes)	No		Proper Clearance:	(Yes)	No	
Masonry/Wall Dowels:	(Yes)	No	N/A	Proper Lap Splice:	(Yes)	No	N/A
Embeds Placed:	Yes	No	(N/A)	Area of Placement free & clear of debris:	(Yes)	No	

**Drawing Detail:** S1.1

**Shop Drawing Detail:** S3.1

**\*Remarks:**

Ernie Kraytenberg  
**Inspector/Technician**  
**John Turner Consulting, Inc.**

Non Compliant

Compliant

Remarks

Fix

**NH MA ME CT VT RI**

**JOHN TURNER CONSULTING**

**CONSULTJTC.COM**

19 DOVER STREET  
 DOVER, NH 03820  
 T 603.749.1841 F 603.516.6851

66 SOUTHGATE STREET  
 WORCESTER MA 01603  
 T 508.505.0126

6 CLINTON AVENUE  
 WESTFIELD MA 01085  
 T 413.642.0138

4775 ROUTE 14, UNIT 3  
 WRJ, VT 05001  
 T 802.295.1100

73 RAINMAKER DRIVE  
 PORTLAND ME 04103-1291  
 T 207.883.7878