CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector		Inspection Date	
ACETO CHARLES D		Suzanne Hunt		5/4/2009	
Locatation CBL		Status		Inspection Type	
744 BRIGHTON AVE	259 B060001	Re-Inspect 30 Days		Building Permit-Legalize Nonconf	
Code Int	/Ext	Floor U	Jnit No.	Area	Compliance Date

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date			
1)	6-116.(b)	Interior				06/03/2009			
	Violation:	Egress							
	Notes:	Stairway from 2nd floor to 3rd floor (back of building) is required to have a continuous handrail. height of handrail measured shall be uniform, not less than 34 or more than 38 inches. With graspable rail per code. IBC 2003 1009.11.1							
2)	6-116.	Interior				06/03/2009			
	Violation:	Minimum standards for safety.							
	Notes:	all storage from egress paths must be	e removed						
3)	6-111.(d)	Interior				06/03/2009			
	Violation:	Maintenance of plumbing fixtures.							
	Notes:	Pressure relief value above an unfinished floor shall terminate not more than 12 inches or less than 6 inches above floor. Plumbing Code 608.5							
4)	6-116.(e)	Interior			Basement	06/03/2009			
	Violation:	Fire Protection							
	Notes:	Paper on insulation in basement ceiling must be removed or covered							
5)	6-116.(e)	Interior				06/03/2009			
	Violation:	Fire Protection							
	Notes:	furnace in basement requires sprinkle	er head						

Comments:

continuous rail needed floor 2 to 3 back stair case , pressue relief discharge pipe is currently incorrect, paper backing on insulation (basement) must be removed or covered, sprinkler over furnace required