

Contractor said  
frontal setbacks were checked  
by ~~and~~ other inspection.

9.24.03 Did framing Insf.  
window egress ok 835 ft<sup>2</sup>

went over railing requirement  
framing ok Plumber & electrical  
ok now

12/19/03 - Deck risers on front + rear  
stairs - need graspable rail on  
front + rear stairs - Interior - OK -  
Told Builder. TM

1/6/04 Risers/handrails installed to code -  
Needs permit for gas fired Rental Unit

1/9/04 ~~and~~ Called, met 10/10/04 the footing/frost wall  
& Setback Inspectors -  
Verified Setbacks ok  
Contractor dug out section of frost wall to  
footing - Verified footings & frost wall  
ok to Close

---