

COMMENTS

4-10-00 check setbacks without property pin it. left side 10' to fence, right side over 8' to corner of house, rear 30' to fence. left note to call we and not to four until property lines are established. JB

4-11-00 checked with Mike N. & Jan R. for pins. located neighbors across the street at #30. Siting that pin back into the yard offset the property 10', making the ramp within the setback. The map from PW shows the street line of 50' to determine the 100' of lot length. Went to register of deeds and found the development plan with lot lines. Scaled off plan that shows #30 Eastlawn boundaries are offset from #29. JB

4-12-00 Check dimensions w/ Tom R. 100' back from #30 pin in line and across #29 yard to fence which measured 67' which determines the ~~the~~ ramp is allowable as placed. JB

4-12-00 Reconstruction on Phare w/ Denis - he understands code requirement for clear width, rail heights & spacing, handrail 2 sides, 60"x60" landings JB

5-10-00 Ramp inspection - all measurements width, landings, guards, spaces good Handrail both sides, non-skid surface. Need light at rear door and exit per code 1207.2 JB

5-11-00 spoke with Denis (family member). He is disconnecting the light currently wired & switched inside to shed to a light post at the switch back on the ramp JB

Inspection Record

Type

Date

Foundation:

Framing:

Plumbing:

Final:

Other: