CONCERNING ELECTRICAL WORK AT 1445 FOREST AVE:

ISSUES ADDRESSED

- 1. All knob and tube wiring in basement removed and circuits re-fed with connections made in junction boxes.
- 2. All outlets on first, second, and third floor checked for proper grounding and corrected where necessary.
- 3. All circuits checked for proper fusing.
- 4. Upgraded service to 3 meters and 3 panels to provide for a house meter. Grounding to water main to be brought up to current code at that time.
- 5. Second floor outlets were checked for proper grounding, outlets replaced where needed.
- 6. Second floor--checked circuits for proper fusing Installed 2 additional small appliance circuits to separate load.
- 7. Separated and transferred circuits for washer, dryer, basement lights, hall lights, and garage sub panel to the house panel.
- 8. Install smoke detector in second floor bedroom.

All safety and code issues have been addressed except where noted.

Jeffrey P. Williams Williams

Low Real C.

2078748060