

•  
•  
•  
•  
•  
•

389 Congress St.  
Portland, ME 04101  
Phone: (207)874-8700  
Fax: (207)874-8716

facsimile transmittal

**To:** Glen Gervais **From:** Mike Nugent/ Manager of  
Inspection Services


**Fax:** 892-1383 **Date:** December 21, 2001

**Phone:** 892-3149 **Pages:** 1

**Re:** Pannel Ave. (347 A005) **CC:**

Urgent  For Review  Please Comment  Please Reply  Please Recycle

• • • • • • • • • •



Preliminary Plan Review Questions:

1) What is being used as the beam in the in the second floor system above the “dining room” entry.

2) Foundation stepdown on daylight side is not shown.

3) Headers above 1<sup>st</sup> floor “back door” and Basement Slider.

4) Code Compliant protection for the 1<sup>st</sup> floor “back door”

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



• • • • • • • • • • • • • • • • • • • •