

Memo

To: Dwight Brackett
From: Mike Nugent
Date: 06/18/2002
Re: 11 Haskell St. (339 F007)

The following information must be provided prior to the release of Permit #020515 for a single family home:

- 1) Height of Guards and baluster spacing for the farmer's porch rails, roof rafter size, spacing and fastener detail .
- 2) Rear Steps are not on the site plan and are not approved. Marge Schmuckal and Jay Reynolds must approve this. Consequently the rear door cannot be approved without code compliant protection.
- 3) The 8' spacing of the lally columns is excessive w/ 3 - 2" x 12" girder.
- 4) The spacing of the farmer's porch carrier is excessive.
- 5) Beam Info not clear
- 6) Header detail for the 5' and 6' openings in the first floor floor plan, bearing wall
- 7) Are the 3046 Windows egress approved
- 8) Attic access ?
- 9) Garage fire rating , walls and ceiling? Detail and what kind of door?
- 10) Open or closed interior stairways? Handrail/guard rail details