CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

February 2, 2018

Blue Atlantic Portland LLC 500 N DEERBORN STE 400 CHICAGO IL 60654 BAYSIDE VILLAGE 132 MARGINAL WAY PORTLAND ME 04101

Location	CBL	Inspection Date
132 MARGINAL WAY	442 A001001	12/6/2017
Inspector	Inspection Type	Status
Curtis Magnuson	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 2/28/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.9.1.1 EMERGENCY LIGHTING REQUIRED; Emergency lighting facilities for means of egress shall be provided in accordance with Section 7.9 for the following: (1) Buildings or structures where required in Chapters 11 through 43 (2) Underground and limited access structures as addressed in Section 11.7 (3) High-rise buildings as required by other sections of this code (4) Doors equipped with delayed-egress locks (5) Stair shaft and vestibule of smokeproof enclosures, for which of the following also apply: (a) The stair shaft and vestibule shall be permitted to include a standby generator that is installed for the smokeproof enclosure mechanical ventilation equipment (b) The standby generator shall be permitted to be used for the stair shaft and vestibule emergency lighting power supply (6) New access-controlled egress doors in accordance with 7.2.1.6.2 All of the emergency lights that were tested failed to operate.	
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. The fire department requires one, hardwired with battery back up, CO detector in the common area of each unit.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 7.2.1.8.1 DOORS SHALL BE SELF-CLOSING & SELF-LATCHING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise specified by 7.2.1.8.3. The stairwell door on the 1st floor will not close on its own. This door is located near the elevator.	

Violation		Proposed Date of Completion
normally required to be kept closed	LL BE SELF-CLOSING & SELF-LATCHING; A door leaf I shall not be secured in the open position at any time and losing in accordance with 7.2.1.8.2, unless otherwise	
Some of the center hallway fire doodoors, when they are in the closed	ors do not close when the panic bar is activated. Also the position, do not latch.	
issued by the AHJ and shall bear the designated representative. In additing activities for which the permit is issued to be conducted (3) Name and activities.	nspection sticker required; Permits shall be ne name and signature of the AHJ or that of the AHJ's ion, the permit shall indicate the following: (1) Operation or ued (2) Address or location where the operation or activity ddress of the permittee (4) Permit number and date of e permit (6) Inspection requirements and other permit	
FINAL DATE OF COMPLETED VI	OLATION(S)	//
FIRE PREVENTION BUREAU RE	-INSPECTION OF COMPLETED VIOLATION(S)	//
questions. VIOLATOR CERTIFICATION I agree to remedy the violations understand that I must contact the is entirely within the Bureau's distributed in the standard that it is might be a supplied to the supp	listed within the timeframes provided. If I require add he Fire Prevention Bureau <u>prior to the deadline</u> to requ iscretion to grant or deny. y responsibility to schedule a reinspection of my prope	itional time to comply, he itional time to comply, he it is an extension, which it is the violations
have been remedied to do so. M violations have not been remedie	y failure to schedule a reinspection shall be deemed an ed.	admission that the
	ement, I understand that I am liable for penalties pursus 3 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be .	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	