

## CERTIFICATE

0 F

### COMPLIANCE

CITY OF PORTLAND

June 23, 1980

Department of Neighborhood Conservation And Inspection Services Housing Inspections Division Telephone: 775-5451 - Extension 448 - 358

Greenwood Lane Portland, Maine 04103
Re: Premises located at
A re-inspection of the premises noted above was made on
This is to certify that you have complied with our request to correct the violation of the Municipal Codes relating to housing conditions as described in our "Notice of Housing Conditions" dated  August 17, 1970
Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.
In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every five years. Although a property is subject to re-inspection at any time during the said five-year period, the next regular inspection of this property is scheduled for
Sincerely yours,
Joseph E. Gray, Jr. Director Neighborhood Conservation And Inspection Services

Inspector Outher

Arthur Addato

1/22/79 - LOAN

ADMINISTRATIVE MEASURE DECISION Department of Neighborhood Con Date November 22, 1978 William A. III and/or Michael L. Reagan, Atals Portland, Naine 04103 Re: Premises located at 27 Anderson Street, Portland, Maine NCP-East End 13-D-3 You are hereby notified that <u>a reinspection and your reguest for additional lime</u> referred premises resulted in the decision noted below. XX Expiration time extended to Jan. 22, 1979 in order to complete the work in progress to correct the remaining forty three (43) Housing Code violations es shown on the attached Notice of Housing Conditions dated Aug. 17, 1978. Notice modified as follows. \_\_\_ Please notify this office if all violations are corrected before the above mentioned dates, so that a "Certificate of Compliance" may be issued. Very truly yours, Joseph E. Gray, Sr., Director Neighborhood Conservation Enc1.

Chief of Housing Inspections

City of Portland

Housing Inspections Division Telephone: 775-5451 - Ext. 448 - 358

Dear Sirs:

on Nov. 20, 1978, regarding our "Notice of Housing Conditions" at the above

In Attendance: Michael E. Reagan Arthur Addato

## NOTICE OF HOUSING CONDITIONS

		DU
City of Portland Department of Neighborhood Conservation Housing Inspections Division Tel 775-5451 - Ext. 358 - 448 William A. III and/or Michael E. Reagan, etals Greenwood Lane Portland, Maine 04103 773-5894	Ch -RlLot: Location: Project: Issued: Expired:	27 Anderson Street NCP-East End August 17, 1978
Dear Nessrs. Reagan:		
An examination was made of the premises at 27 Ander.  Maine. by Housing Inspector Addato . Viol to housing conditions were found as described in detail	ations of Muni	, Portland, cipal Codes relating
In accordance with provisions of the above mentioned Conthese defects on or before November 17, 1978 arrange a satisfactory repair schedule if you are unable specified time. We will assume the repairs to be in provided that the premises have been brought into complease contact this office if you have any questions results.	You may contact the to make such cogress if we do thin the time so apliance with C	et this office to a repairs within the do not hear from you set forth above, will code Standards.
Your cooperation will help this Department in its goal in decent, safe and sanitary housing.	to maintain al	l Portland residents
RE 11/20/28 QA	Very truly yo Joseph E. Gra Neighborhood	y, Jr., Director
Inspector <u>Orthur Addato</u> A. Addato	Lyle D. Noyes	HUW RM.
EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARD	S FOR HOUSING"	- Section(s)
(1) 1 OVERALL FOUNDATION - replace missing mortar and b	rick.	
124 2 PROVE CHANKEL ment one minoring monter and bricker		
140 2 PEAR CUITOUEN and and minding marker and inviole		<del></del>
0/94 4. OVERALL CELLAR WINDOW replace missingsloss.		
5. OVERALL ROOF - replace worn and missing shingles.	ricons fatmio	17A-17
// 7: CFLLAN STAIRS - replace missing handrail:	-reero-a-ourri	3d
1/14 - CELLAR STATE WALL replace missing plaster.		3b
1/4 0 FROM CHILD CHILDRY - remove soot and property of	icooc-of-it-	36
-//x-/ +0EPT FRONT CELLAR WALL - remove illegal wiring at	che-c <del>leetrl</del> o-	pana4
1/4 - 11 - TEPT FRONT CELLAR WALL - replace missing electric	-panel_cover.	
1/4/ 12- OVERALL CELLAR HALL - replace missing function bo	X-covers	<del></del>
//z:/-19OVERALL CELIAR FLOOR - clean up debris and proper	- <u>lv-diepoee-o≨-</u>	<u>it4</u>
14. SECOND FLOON REAR- HALL STAIRS - replace inoperation	<del>.ve-rear-egress</del>	
continued		

#### SECOND FLOOR

2 12 15. FRONT BEDROOM WALL - replace missing plaster.	
2/22 * 16. FROMT BEDROOM WINDOW - replace rotted sash.	——————∴C
10/2% 17. PROMI BEDROOM WINDOW - replace broken glass.	~ <del>~~~~~~~</del>
10/24 18, FRONT BEDROOM FLOOR replace missive floor covering.	
2-10 (-FRONT REDROCM WALL - remove Deeling Deint.	
12220 LIGHT MIDDLE - BEDROOM WALL remove peeling paint.	<del></del>
7/22-21 rateur MIDDLE REDROOM WINDOW - replace rotted sash.	3c-
16/24 22.4 RIGHT MIDDLE BEDROOM FLOOR — replace missing floor covering.	3b
1214 22 AFER MIDDLE REDROOM OF THE INC. PER 1981 NG 112NU TINGUTE.	80
114 2/ IEEE MODIE REPROM FIAGE - replace missing floor covering	3b
2/2 25. LEFT MIDDLE - DEDROOM WALL - replace missing duplex outlet cover.	
2/32 * 264 PATHROOM WALL - replace mirsing plaster.	3b
7/2 200 Million William College Migating agent	3c-
7/2 18 27. MATHROOM WINDOW replace missing each.	3b.
2/22 28: BATHROOM CEILING remove or replace loose plaster. 2/12 29. REAR BEDROOM CEILING remove perling paint.	3b
The service of the se	<del>3</del> b_
2/2 230 LEEAR BEDROCH WALL - remove packing points	

#### FIRST FLOOR

```
/// * 31. REAR BEDROOM WINDOW - replace missing each
10/24 32: FRONT HALL WALL remove peeling paint.
10/24 33: FRONT HALL CELLING remove peeling paint.
10/24 35: FRONT HALL STAIRS replace missing balusters
10/24 35: FRONT BEDROOM WALL remove peeling paint.
                                                                                                                                                      3<del>6.</del> )
                                                    remove or replace loose plaster
   //* 36. FRONT BEDROSM CEILING
        ST. TRONT BEDROOM WALL replace missing placter
10/2# 38. FRONT BEDROOM WALL - replace missing duplox outlet-cover
                                                                                                                                                     35.
     794 39. LIVING ROOM GIALING - replace missing planter.
   ///* 40. BATHROOM repisce tessing lavatory; shower and flush soilet.

4/// 41_KTGHTN CEILING remove peeling paint.

4/// 42_KTGHEN CEILING replace micsing light fixture.
                                                                                                                                                     -6d
   4///* 43 - KITCHEN-CEILING-
                                           -remove-exposed-electric-wiring.
```

\* WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANES OF THIS STRUCTURE.

We suggest you contact the City of Portland Building Inspection Department, 389 Congress St., Tel. 775-5451 to determine if any of the items listed above require a building or alteration permit.

# NOTICE OF HOUSING CONDITIONS

City of Portland Department of Neighborhood Conservation Housing Inspections Division Ch.-B1.-Lot: 13-D-3 Tel. 775-5451 - Ext 358 - 448 Location · 27 Anderson Street Project: NCP-East End William A. III and/or Michael F. Reagan, etals Issued: August 17, 1978 Greenwood Lane Expired: November 17, 1973 Portland, Maine 04103 773-5894

Dear Messrs. Reagan:

An examination was made of the premises at \_\_\_\_\_27 Anderson Street Maine, by Housing Inspector Addato

Violations to housing conditions were found as described in detail below. Violations of Municipal Codes relating

In accordance with provisions of the above mentioned Codes. You are requested to correct these defects on or before November 17, 1978. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and. on reim vection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this notice.

Your cooperation will help this Department in its goal to maintain all Portland residents in decent. safe and sanitary housing. Re 9/28/28 an

RE Modfor aa

Very truly yours, Joseph E. Gray, Jr., Director & L; hborhood Conservation

Lyle D. Noyes,

Chief of Housing Inspections EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" -OVERALL FOUNDATION - replace missing mortar and brick. Section(s) FRONT CHIMNEY - replace missing mortar and brick. FRONT CHIMNEY - replace missing mortar and brick.

REAR CHIMNEY- replace missing mortar and brick.

OVERALL CELLAR WINDOW - replace missingglass.

OVERALL ROOF - replace worn and missing shingles.

CELLAR STAIRS- replace rotted and broken treads, risers & stringers.

CELLAR STAIRS - replace missing handrail.

CELLAR STAIR WALL- replace missing plaster. Зс 7. CELLAR STAIRS - replace missing handrail.

9. CELLAR STAIR WALL- replace missing plaster.

9. FRONT CELLAR CHIMNEY - remove soot and properly dispose of it.

10. LEFT FRONT CELLAR WALL - remove illegal wiring at the electric panel.

11. LEFT FRONT CELLAR WALL - replace missing electric panel cover.

12. OVERALL CELLAR WALL - replace missing junction box covers.

13. OVERALL CELLAR FLOOR - clean up debris and properly dispose of it.

14. SECOND FLOOR REAR- HALL STAIRS- replace inoperative rear egress.

νw

continued 27 Anderson Street, Portland, Maine NCP-EE 13-D-3 8/17/78 SECOND FLOOR \* 15. FRONT BEDROOM WALL - replace missing plaster. \* 16. FRONT BEDROOM WINDOW - replace rotted sash. \* 17. FRONT BEDROOM WINDOW - replace broken glass. \* 17. FRONT BEDROOM WINDOW - replace broken glass.

\* 13. FRONT BEDROOM PLOOR - replace missing floor covering.

19. FRONT BEDROOM WALL - remove peeling paint.

20. RIGHT MIDDLE - BEDROOM WALL - remove peeling paint.

\* 21. RIGHT MIDDLE BEDROOM WINDOW - replace rotted sash.

\* 22. RIGHT MIDDLE BEDROOM FLOOR - replace missing floor covering.

\* 23. LEFT MIDDLE BEDROOM CEILING - replace missing light fixture.

\* 24. LEFT MIDDLE BEDROOM FLOOR - replace missing floor covering.

\* 25. LEFT MIDDLE - BEDROOM WALL - replace missing duplex outlet cover.

\* 26. BATHROOM WALL - replace missing plaster. 3b 3b 3b 3c 3b 8e 3b \* 25. LEFT MIDDLE - DEDKOOT WALL - replace missing duplex \* 26. BATHROOM WALL - replace missing plaster. \* 27. BATHROOM WINDOW - replace missing bash. 28. BATHROOM CRILING - remove or replace loose plaster. £'e 3Ł 3¢ 35 3b 29. REAR BEDROOM CEILING - remove peoling paint. 30. REAR BEDROOM WALL - remove packing paint. FINST FLOOR \* 31. REAR BEDROOM WINDOW - replace missing sash. 31. REAR BEDROOM WINDOW - replace missing bash.

32. FRONT HALL WALL - remove peeling paint.

33. FRONT HALL CEILING - remove peeling paint.

34. FRONT HALL STAIRS - replace missing llusters.

35. FRONT BEDROOM WALL - remove peoling paint. 3c 3b 3b \* 36. FRONT BEDROOM CEILING - remove or replace loose plaster. 3b 3b 37. FRONT BEDROOM WALL - replace missing plaster.

\* 38. FRONT BEDROOM WALL - replace missing duplex outlet cover.

39. LIVING ROOM CEILING- replace missing plaster. 3ь 8e # 40. BATHROOM- replace missing lavatory, shower and flush toilet.

41. KITCHEN CEILING- remove peeling paint.

42. KITCHEN CEILING - replace missing light fixture.

43. KITCHEN CEILING - remove exposed electric wiring. 3ъ 6d 3Ъ

\* WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAVETY OF THE OCCUPANTS OF THIS STRUCTURE.

We suggest you contact the City of Portland Building Inspection Department, 389 Congress St., Tel. 775-5451 to determine if any of the items listed above require a building or

				-				
REINSPECTION	RECO	MMENDATIONS		K	LOC	ATION 27	andraga	
INSPECTOR (	2	A CONTRACTOR OF THE PARTY OF TH	BYCRE	Cont.	PRO	JECT ZZC	PEE	
THOTACIOK_(	A WOOD CO.		DATES	20/50	OWN	er O	a.	_
NOTICE OF HO	HCTNO		And a second second second second			Tan		
Issued		CONDITIONS xpired	HEARING NO	TICE Expired			L NOTICE	
8/17/7	8/	1/17/78				Issued	Expired	
A reinspection	on war	s made of the ab	ove premises an	d I recomme	and the fo	allowing not	- L	_
DATE	7	ALL VIOLATI	ONS HAVE BEEN C	ORRECTED	- 1	orrowing act	100:	_
6/20/80	a	Send "CERTI	FICATE OF COMPL	IANCE"		P(	OSTING RELEASE	-
6/20/00	2,4	SATISFACTORY R	Rehabilitation i	n Progress				_
11/20/78	20					Van las		
10/0/00		Time Extended						-
10/24/18	200	Time Extended	To: 12/27	17407	XGQ	07	5/24/80	30
1/11/8a	SP 182	Time Extended	To: 2/1/8	D-07	3.0	1574		
		UNSATISFACTORY	, ,			0 7-7(	6/29/2003	
		Send "HEARING	NOTICE"			"FINAL NO	TICE"	
		"NOTICE TO VACA	ATEL					
		POST Entire				_		
		POST Dwelling	Units					
	<del> </del>	UNSATISFACTORY	Y Progress			<del></del>		
·		"LEGAL ACTION"	' To Be Taken	·				
9 /28/76	an	INSPECTOR'S RE	EMARKS: Pe/c	0/600	VY A#	20110	*	
11/20/28	aa	Celio d- au	ردريد ورم مردو مي الإراق بالمصافية	وسيقتصر فيحرفتن والمعركين والم	On other days	ويه معرمور التدريب	genera Mangkan pa	
4/11/20	aa	RE/CO	BELOL	OGRESS,	THEPE	FORE TX	INSTEADOF HN	,
	157.70	BEIDIN	REHAD.	-014N La	· pulmag.	١ - ١٠٠٠ منابل		
7/30/39 10/22/19 10/24/79	1200	REIS N	9-15/15	>~				
מכלעד לפין	70	RF/col:	23 mil Co	d2 7"×	60-	Cancell	et lean	
111/80	aa	PF/co-	23 well Co	103. 2.0 A	every a service	. 0TX	(- 39	
2/22/80	aa	Brian-	SP- W/1	- X G	<u> </u>			
W/W / W - /	aa	BF last w	23 mil co 5 P- WIF WIP- 50	<u> </u>	<u> </u>			
119/80	a a	INSTRUCTIONS TO	O INSPECTOR:			· · · · · · · · · · · · · · · · · · ·		
							3	
1	l							