Inspection Services
P. Samuel Hoffser
Chief



Planning and Urban Development
Joseph B. Gray Jr.
Director

CITY OF PORT AND

NOVEMBER 07, 1996

RSB LIMITED LIABILITY COMPANY 32 PYA RD PORTLAND ME 04103

> Re: 129 COMMERCIAL ST CBL: 029- - D-001-001-01

DU: 5

Dear Sir:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referred property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code. We did, however, note the following Items that could cause future problems:

1. INT - 2MD FL - APT #2 KITCHEN
GROUND FAULT INTERRUPTER IS MISSING

2. INT - REAR STAIRS - 108 40

THERE ARE NO HANDRAILS
3. INT - FRONT STAIRS -

108.40

113.50

A SECTION OF THE HANDRAIL IS MISSING

4 INT - OVERALL - 113.50
HARD-WIRED BATTERY-BACK/UP SMOKE DETECTORS ARE REQUIRED IN EACH UNIT

Good maintenance is the best very to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,

Arthur Rowe

Code Enforcement Officer

Tanımy Munson

Code Enfc Offc./ Field Supv.

Turning Thurson

- and an artist of the state of