045 plackell Stree

NDPREMAB II

SILE ALIE



PAUL M. FOLAN Clairman
PAUL M. FOLAN Clairman
PHORACE M. BUDIV. Vice Chairman
JOHN H. MALCONIAN
THE REVEREND HAROLD A. MCELWAIN
CHARLES W. REDMAN, JR.

THOMAS F. VALLEAU, Executive Director

ROOM 315, CITY HALL PORTLAND, MAINE 04111 775-5451

Loc. 84 1/2 Rear Brackett Street Proj: NDP 2 Block 57E Issued: November 12, 1971 Expires: December 12,

Mr. Michael Kopack 84 1/2 Rear Brackett Street Portland, Maine

Dear Mr. Kopack:

An examination was made on November 9, 1971 of the premises located at 84 1/2 Rear Brackett Street, Portland, Maine by Rehabilitation Specialist Max Furrer. Violations of Municipal Codes relating to housing conditions were found as described below.

In accordance with the provisions of the above named codes you are required to correct these defects. Some repairs or improvements will require permits which are obtained from the Building, Health, Fire or other City Departments.

Financial assistance and construction advice are available from the federal government, by contacting the Neighborhood Development Program office at 247 Danforth Street, 774-3611. Please call us to discuss the e before beginning work on your property.

Very truly yours,

Joseph & Hary, In Con Ray

Profect Director Towner

BY

Chief, Rehabilitation Services

VIOLATIONS

HOUSING CODE REFERENCE

Exterior

- Repair or replace the defective brick and mortar on chimney above roofline.
- 2. Repair the blistered, cracked or peeling paint on all exterior casings and trim.
- 3. Repair or replace deteriorated steps at rear.