


RIFIELD ROAD, PEAKS ISLAND

E4-E-2



POST OFFICE DEPARTMENT  
OFFICIAL BUSINESS

PENALTY FOR PRIVATE USE TO \$100  
PAYMENT OF POSTAGE, \$3.00

POST-DATE OF  
DELIVERING OFFICE

PORTL

1962

RETURN  
TO

INSTRUCTIONS: Fill in items below and com-  
plete #1 on other side, when applicable. Mohen  
gummed ends and attach to back of article. Print  
on front of article RETURN RECIPIENT REQUIRED.

REGISTERED NO.

54236

NAME OF SENDER

Building Inspection Department

CLASSIFIED NO.

STREET AND NO. OR P. O. BOX

INSURED NO.

Room 110, City Hall

CITY, STATE AND ZIP

Portland, Maine

C15-15-71944 4

# #1-INSTRUCTIONS TO DELIVERING EMPLOYEE

Deliver **UNFLYED** to **ADDRESSEE**  Show address where delivered  **FLYED** (Additional charges required for these services)

## RETURN RECEIPT

Received the numbered article described on other side.

**SIGNATURE OR NAME OF ADDRESSEE** (and always be filled in)

**SIGNATURE OF ADDRESSEE'S AGENT, IF ANY**

DATE DELIVERED

ADDRESS WHERE DELIVERED (only if requested in Item #1)

CSB-10-2154-4 GPO



## R3 RESIDENCE ZONE

CITY OF PORTLAND, MAINE  
DEPARTMENT OF BUILDING INSPECTION

## COMPLAINT

INSPECTION COPY

COMPLAINT NO. 60/81

Date Received Cottage

Location:

Byfield Rd., Peaks Isl.

Location Byfield Rd., Peaks Island 84-E-2 Use of Building Cottage  
Owner's name and address Robert W. & Catherine C. Penney Telephone 3-3905  
Tenant's name and address 29 June 1963 Telephone  
Complainant's name and address Telephone

Description: Chimney has no footing and the building is completely open on the underside. The rear porch is in bad condition and the exterior of the building is generally bad. Building is dilapidated.

NOTES: No work started on demolition. ESS.

11/10/60 - Report Pre E.S.D.

Stairway to front porch, rotted Cedar posts supporting cottage otherwise nearly all rotted causing collapse. Post, 1 x 10, 2 x 4, floor timbers fair. Boarding from sill to ground 2 1/2-4' bulged and rolled in sections. Chimney split clear through (removable) and ends up short. Deceitful by straps attached to building. Rear porch completely rotted. Holes in roof. Front porch leaning to right.

11/14/60 - See letter to owner - AGJ

4/5/61 (4/5/61) No work seems to have been done - G.C.M.

4/24/61 - Second letter to owners - AGJ

5/2/61 - Spoke with Mrs. Penney who said that they had no money nor her husband any time to fix property up. While 1960 taxes were paid, property was sold to City of Portland for non-payment of 1959 taxes on Feb. 1, 1960 - AGJ

9/6/63 - mostly done

5.8.8

84-E-2

RYEFIELD ST

RYEFIELD STREET

1 2 3 4 5

SEASIDE AVENUE

WATER

Optl.- 60/81 - Ryfield Road, Peaks Island (Assessors Lot No. 84-E-2)

Nov. 14, 1960

Robert R. & Catherine G. Penney  
39 Tyng Street

Dear Mr. & Mrs. Penney:

An inspector from this department after a recent examination of the cottage at the above named location, of which you are reported to be the owners, made the following report:

"Stair treads to front porch rotted, Cedar posts supporting cottage structure nearly all rotted causing cottage to list to the left. Floor timbers fr. Boarding from sill to ground two to four feet bulged and rotted in sections. Chimney split clear through (horizontally) and unsupported except for straps attached to building. Rear porch completely rotted out. Hole in roof. Front porch leans to right."

This report seems to indicate that the entire building must be in a state of disrepair. The condition of the foundation of the building, the chimney, and the porches is particularly dangerous. In fact it may be that the condition of the entire structure is such as to make demolition advisable. As authorized and directed by Section 109-a of the Building Code of the City of Portland (copy enclosed herewith) you are hereby directed to have made before Dec. 15, 1960 such changes, repair or alterations as are necessary to correct these dangerous conditions. If you should decide to demolish the building, a permit from this department is required before work is started. However, nothing in this order is to be considered as preventing the taking of immediate steps without a permit to make safe temporarily any part of the work which appears to be immediately dangerous.

Very truly yours,

Albert J. Sears  
Inspector of Buildings

AJS:tm

FU 5/2/61 AJS

Rec'd. Mail  
Rec'd. Receipt

Cottage - 60/61 - Ryfield Road, Peaks Island (Assessor's Lot No. 84-E-2)

April 26, 1961

Robert R. & Catherine G. Penney  
23 Winter Street

Dear Mr. & Mrs. Penney:

Last fall I wrote you concerning the unsafe condition of certain parts of the cottage at the above named location, of which you are reported to be the owners. An inspector from this department reported that at the time of a recent inspection he could not see that anything had been done to correct the dangerous conditions.

Please let me know before May 2, 1961 what you plan to do in regard to the order issued in my letter of November 14, 1960 under the Building Code so that I can determine what further steps, if necessary, I should take to have the dangerous conditions corrected.

Very truly yours,

Albert J. Sauro  
Inspector of Buildings