




Reviewed for Code Compliance
Permitting and Inspections Department
Approved with Conditions

01/22/2019



island to
Replace non-load
Bearing wall



Reviewed for Code Compliance
Permitting and Inspections Department
Approved with Conditions

01/22/2019

45 Eastern from unit 9K
Existing

