CITY OF PORTLAND

FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

January 17, 2018

Cathleen Murray 91 BECKETT ST PORTLAND, ME 04101

| Location | CBL | Inspection Date |
|---------------|-----------------------|-----------------|
| 91 BECKETT ST | 003 G014001 | 12/13/2017 |
| Inspector | Inspection Type | Status |
| Sean Donaghue | FP Routine Inspection | Failed |

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 2/15/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

| Violation | Proposed Date of Completion |
|---|---|
| NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. 1st and 3rd floor apartments, as well as basement. On 12/13/2017, all CO alarms were found | IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed. |
| installed except for the basement. NFPA 1 EXCESSIVE/DISORDERLY STORAGE ; Reference NFPA 1 for excessive fuel-load. | |
| Washer dryer is not permitted in egress stairs, no storage permitted in any egress stair. | / |
| NFPA 70- ARTICLE 110 B CERTIFY ELECTRICAL SYSTEM ; Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling. Entire electrical system needs to be looked at. | / / |
| Notable issues in basement related to knob and tube, open junction boxes, open wiring connections, etc. Please have certified by electrician. | |
| FINAL DATE OF COMPLETED VIOLATION(S) | / |
| FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S) | , , , |
| | // |

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, I understand that I am liable for penalties pursuant to the City of Portland Code of Ordinances §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal action.

| Date | Responsible Party |
|-----------------|------------------------|
| Date | Responsible Party |
| SEEN AND AGREED | |
| Date | Fire Prevention Bureau |