CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

July 24, 2018

PORTLAND VOA ELDERLY HOUSING INC 3939 CAUSEWAY BLVD METARIE LA 70002

| Location | CBL | Inspection Date |
|--------------|-----------------|------------------------|
| 158 NORTH ST | 010 C001001 | 3/1/2018 |
| | | |
| Inspector | Inspection Type | Status |

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 8/15/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

| Violation | Proposed Date of Completion |
|---|--|
| NFPA 101- 9.7.4.1 FIRE EXTINGUISHERS REQ- OTHER; Where required by the provisions of another section of this code, portable fire extinguishers shall be installed, inspected, and maintained in accordance with NFPA 10, Standard for Portable Fire Extinguishers. Fire extinguisher in electrical room needs to be mounted on wall. | // |
| NFPA 70- ARTICLE 590.6 EXT. CORD USED FOR PERMENANT WIRING; Ground-fault protection for personnel for all TEMPORARY wiring installations shall be provided to comply with 590.6 (A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment or similar activities. Extension cord used to run refrigerator in basement kitchen. Lights run by extension cord in basement shop. | |
| NFPA 30- TABLE 9.6.2.1 FLAMMABLE/COMBUSTIBLE LIQUIDS STORAGE EXCEED LIMIT; See NFPA 30 Table 9.6.2.1 for special occupancy limits for flammable and combustible liquid storage. Aerosol paint cans need to be in rated storage cabinet. | IMMEDIATELY remove all excess flammable/combustible material from the interior of the structure. Your signature below indicates that all excess material has been removed, will not be replaced, and will be properly disposed of or stored elsewhere. |

| Violation | | Proposed Date of Completion |
|--------------------------|---|-----------------------------|
| FINAL DATE OF COMPLETED | VIOLATION(S) | // |
| FIRE PREVENTION BUREAU F | RE-INSPECTION OF COMPLETED VIOLATION(S) | // |
| | to reject or modify any proposed plan of action, and meal capacity to complete the proposed plan. Please continuous | |
| • | as listed within the timeframes provided. If I require a the Fire Prevention Bureau <u>prior to the deadline</u> to re discretion to grant or deny. | |
| v | my responsibility to schedule a reinspection of my pro My failure to schedule a reinspection shall be deemed died. | |
| | reement, I understand that I am liable for penalties pur §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may b | • • |
| Date | Responsible Party | |
| Date | Responsible Party | |
| SEEN AND AGREED | | |

Fire Prevention Bureau

Date