Lee Urban- Director of Planning and Development Michael J. Nugent- Inspections Division Director

November 30, 2005

MCADAM THOMAS J 92 EXCHANGE ST PORTLAND, ME 04101

CBL: 012 G019001 Located at 87 WALNUT ST **Hand Delivery** 

Dear Dottie Seavey,

## STOP WORK ORDER

An evaluation of the above-referenced property on 11/29/2005 revealed that building construction was being conducted without benefit of a valid building permit as required by Section 105.1 of the 2003 International Building Code and the 2003 International Residential Code of the City of Portland.

Appropriate permitting has not been issued for the property listed above, therefore all construction activity at that property must STOP immediately. This is a STOP WORK ORDER pursuant to Section 114. of 2003 International Building Code and the 2003 International Residential Code of the City of Portland.

You may resume construction activity only after issuance of the appropriate building permit and the subsequent lifting of this order. Building Permit Applications are available in this office, Room 315 at Portland City Hall, from 8:00 a.m. to 4:00 p.m. weekdays except holidays.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A of M.R.S.A. Section 4452. This constitutes an appealable decision pursuant to Section112 of the City of Portland Building Code.

If you wish to discuss this matter, or you have any questions, please feel free to contact me.

Sincerely,

Jeannie Bourke @ (207) 874-8715 Code Enforcement Officer