

FAX COVER SHEET

New Meadows Abatement
P.O. Box 227
Bath, ME 04530

(207)443-1071
(207)443-1613 FAX

SEND TO Company name	Wright - Ryan		From	
Attention	re: Red Fox Properties	Date	2-28-14	TIME 12:32 pm
Office location		Office location	West Bath	
Fax number	773-5173	Phone number	443-1071	Fax Number 443-1613

Urgent
 Reply ASAP
 Please comment
 Please review
 For your information

Total pages, including cover: 4

COMMENTS

IF YOU DO NOT RECEIVE ALL PAGES, PLEASE CALL 207-443-1071. THANK YOU!!

Clearance: 79 Walnut St, Portland

I will not have paperwork for 1 East Cove Portland until Monday

Thank you
Pan Hamilton
Office Manager

**ICON ENVIRONMENTAL CONSULTANTS
FINAL CLEANING CHECK LIST**

DATE: 2/27/2014 TIME: 0950 LOCATION: First floor

PROJECT NAME: 79 Walnut Street Portland, Maine

JOB NUMBER: NMA 14-02-05

CONTRACTOR: New Meadows Abatement PROJECT MONITOR: C. Wilson AM-0019

FINDINGS	YES	NA*	NO*
1. Visible ACBM removed, equipment, supplies, waste.	X		
2. Required poly barriers in good condition (no tears).	X		
3. Surfaces wet wiped, substrate touched to confirm.	X		
4. Design and Notification on site.	X		
5. Negative pressure system operating at/above .02/H ₂ O	X		
6. Wall, ceiling, (floor), pipe, boiler, duct Seams, gasket, fitting, tank visual pass? (-) = Material Abated	X		
7. Does containment match design?	X		
8. Area dry for air test?	X		
9. Has Monitor signed on containment log?		X	

REMARKS *(All NO/NA responses require further explanation)

(Indicate deficiencies and locations)

Approximately 120 square feet of floor tile

Completion of post tear down visual Yes/(No) Pass/Fail

Quantity of Asbestos Abated: see above

Visual inspection: Passed X Failed

Air Results: Passed X Failed Date: 2/27/2014 No. of Samples 3

PROJECT SUPERINTENDENT: *PJ Dill*

ICON ENVIRONMENTAL CONSULTANTS

Final Cleaning Check List Rev. 06/07 207-458-7143, Iconenviro@aol.com

ICON ENVIRONMENTAL CONSULTANTS
526 WEST RIVER ROAD SUITE 2
AUGUSTA, MAINE 04330
AIR SAMPLE ANALYSIS REPORT
207-458-7143
Iconenviro@aol.com

Client: New Meadows Abatement
 79 Walnut Street
 Portland, Maine

Date: 2/27/2014

Project: First floor 120 square feet of floor tile

Client Ref. Number: NMA 14-02-05

Collected by: Craig Wilson AM-0019

SAMPLE #	LOCATION/NAME	DURATION	AVE. FLOW RATE	LITERS	FIBER COUNT	CONCENTRATION
B-1	Blank	-----	-----	-----	0/100	
C-1	By rear door	1002-1237	16 lpm	2480	14/100	0.003 f/cc
C-2	Driveway side window	1002-1237	16 lpm	2480	10.5/100	0.002 f/cc
C-3	Walnut street end	1002-1237	16 lpm	2480	12/100	0.002 f/cc
B-2	Blank	-----	-----	-----	1/100	
QA/QC						

Analyst: C. Wilson

Maine DEP #: AA-0016

Client requests disposal of samples (Yes)/No

PCM Analysis performed per NIOSH 7400 method.

Air Sample Analysis Report Rev. 6/07

Log in Date: _____

Log in Storage Date: _____

Waste Date: _____