

Project: Munjoy Heights
Date Prepared: 05/05/2015

Structural Statement of Special Inspections (Continued)

Final Report of Special Inspections (SSIC/SI 1)

[To be completed by the Structural Special Inspections Coordinator (SSIC/SI 1). Note that all Agent's Final Reports must be received prior to issuance.]

Project: *Munjoy Heights*
Location: *79 Walnut St. Portland, Maine*
Owner: *Redfern Munjoy*
Owner's Address: *P.O. Box 8816, Portland, Maine*

Architect of Record: *Ryan Senatore* *Ryan Senatore Architecture*
(name) (firm)
Structural Registered Design
Professional in Responsible Charge: *Aaron C. Jones* *Structural Integrity Consulting Eng.*
(name) (firm)

To the best of my information, knowledge and belief, the Special Inspections required for this project, and itemized in the *Statement of Special Inspections* submitted for permit, have been performed and all discovered discrepancies have been reported and resolved.

Interim reports submitted prior to this final report form a basis for and are to be considered an integral part of this final report.

Respectfully submitted,
Structural Special Inspection Coordinator

Aaron Jones
(Type or print name)

Structural Integrity Consulting Engineers
(Firm Name)

Aaron Jones 5/5/15
Signature Date

