
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager MCINNIS MARTIN T		Inspector Suzanne Hunt	Inspection Date 7/14/2008
Location 34 FOX ST	CBL 012 J003001	Status Re-Inspect 10 Days	Inspection Type Complaint-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 110.26 (B)	Exterior	2		BackYard	
Violation:	NEC 2005/NFPA 70				
Notes:	Egress being used to store garbage. Egress is blocked				
2) 22-3 (a)	Exterior				
Violation:	Rodent Harborage				
Notes:	open and torn garbage bags on second floor egress				
3) 6-109.b	Exterior				
Violation:	Maintenance of shared areas.				
Notes:	property must be maintained in a sanitary manner				
4) 6-109.c	Exterior				
Violation:	Maintenance of supplied facilities				
Notes:	Water tight trash cans must be supplied for tenants				
Comments:	garbage stored on back egress second floor 34 Fox.				