'LLIS IS NOT A BOUNDARY SURVEY This copyrighted document expires 12-13-16. Reproduction and/or dissemination after this date is unauthorized. MORTGAGE INSPECTION OF: DEED BOOK __32237__ PAGE __156__ COUNTY __Cumberland_ PLAN BOOK ____ PAGE ____ LOT ____ ADDRESS: 94 Walnut Street, Portland, Maine Job Number: 911-64 Inspection Date: 09-12-18 Scale: ___1" = 30' Buyers: JP Sheridan, LLC Client File #: __22183.7 Sellers: Anthony C. and Nicholas A. Mancini, Jr. Walnut Street paved drive 2 story brick DOF OVER EXT'S house w\brick foundation DAVID L. J. 124't NOTE: Lines of occupation are shown. A boundary no frontuard setback survey may yield different results. no side yard set backs rear yard set back I HEREBY CERTIFY TO: Jensen, Baird, Gardner, & Henry, JP Sheridan LLC, and Chicago Title Insurance Company.

Monuments found did not conflict with the deed description. APPARENT EASEMENTS AND RIGHTS OF WAY ARE SHOWN. OTHER ENCUMBRANCES, RECORDED OR NOT, MAY EXIST. THIS SKETCH WILL NOT REVEAL ABUTTING DEED CONFLICTS, IF ANY. The dwelling setbacks do not violate town zoning requirements. As delineated on the Federal Emergency Management Agency Community Livingston-Hughes Panel 230051-0014B: Professional Land Surveyors The structure does not fall within the special flood hazard zone. 88 Guinea Road The land does not fall within the special flood hazard zone. Kennebunkport, Maine 04046 A wetlands study has not been performed. 207-967-9761 phone 207-967-4831 fax www.livingstonhughes.com