



OBSERVATION REPORT

TO:	Jake Edwards	DATE:	8/30/2018	TIME:	7:00am
FIRM:	Dayton Group	JOB NO.:	16-0113	PROJECT:	Container Storage
		LOCATION:	Portland, ME		
FROM:		WEATHER:	Clear	TEMP:	83-degree F

- 1) While on site the completed parapet construction was observed and appeared to be in accordance with the contract drawings. While on site the contractor was made aware that the bolts needed to be fully tightened this was resolved on site. All observed work appeared to be in accordance with the contract drawings and was accepted.

SIGNED: 

NAME: Aaron C. Jones, P.E.

This site visit is made to observe the progress and quality of the structural portion of the construction work and to determine whether that work was in general conformance to the structural portion of the Contract Documents. S.I. Inc.'s observations are intended to protect the interests of the Owner and the public. S.I. Inc. is not responsible for the Contractor's work, work methods, safety precautions, timeliness of the work nor any other aspect of the construction for which the contractor has responsibility.