## **CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager STEPHENS CLARK B				Inspector Suzanne Hunt		Inspection Date 6/1/2007	
Locatation CBL			Status		Inspection Type		
31 OXFORD ST			013 B007001	Re-Inspect 10 Days		Complaint-Inspection	
	Code	Int/Ext		Floor	Unit No.	Area	Compliance Date
1)	6-116.2	Interior		1		Hallway	
	Violation:	Egress					
	Notes:	Back Hallway is being used for storage. Egress is blocked from first floor unit. Egress passage mumade clear.					
2)	6-116.3	Interior		1		Hallway	
	Violation:	Egress Obstructions					
	Notes:	als. Egress must be					
3)	6-116.2	Exterior		1			
	Violation:	Egress					
	Notes:	car being stored in side yard entrance is blocking unobstructed egress to safe and open space.					
4)	6-116.3	Interior		1		Hallway	
,	Violation:	Egress Obst	ructions				
	Notes:	Egress to ce	llar is blocked				
5)	6-108.3	Exterior		1		Basement	
	Violation:	Exterior windows, doors and skylights					
	Notes:	Windows in basement are broken. Basement windows must be repaired					
6)	6-108.2	Interior		1	1		
,	Violation:	Interior floors	s, walls, ceilings an	doors			
	Notes:	Back door of apartment 1 has no lock or door knob.					
7)	6-109.2	Exterior		1		back and	side yard
•	Violation:	Maintenance	of shared areas.				•

8) 6-109.2 Interior **Basement** 

Violation: Maintenance of shared areas.

> The basement area is not sanititary. A confirmed (by property owner) sewer issue has resulted in contamination of the basement area. A licensed sanitation company must send evidence of complete

six car batteries, 4 doors, 2 wash machines, Bathtub, tires, broken furniture, construction debris, trash

and all miscellaneauous debris must be removed from around the exterior of the building.

sanitation of basement area.

## Comments:

Notes:

Notes: