CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

0١	wner/Manag	er		Inspector Jeanie Bourke			Inspection Date 1/12/2009	
ST	EPHENS CL	ARK B						
Locatation CBL			Status			Inspection Type		
31	OXFORD ST		013 B007001				Housing-H	ousing Inspection
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date
1)	6-113.(e) Violation: Notes:	Interior Basement Maintenance of lighting fixtures Install junction box covers and remove all non functioning wiring						
2)	6-111.(d) Violation: Notes:	Interior11BasementMaintenance of plumbing fixtures.Repair drainage pipe at tub/shower - trap is not level and pipe pitch is reversed from direction of flow.						
3)	6-116.(e) Violation: Notes:	Interior Basement Fire Protection Install a hardwired, battery backup smoke detector in the basement						
4)	6-108.(c) Violation: Notes:	Interior Basement Exterior windows, doors and skylights All basement window openings shall be repaired to be substantially weathertight and waterproof						
5)	6-108.(a) Violation: Notes:	Interior Basement Foundations cellars, exterior walls, roofs Repair foundation to be substantially weathertight, waterproof and vermin proof as seen at window						as seen at window openir
5)	6-108.(f) Violation: Notes:						Basement heating for s	afe working condition.
7)	6-117 Violation: Notes:	Interior 1 Inspections Unit 1 shall be inspected at the scheduled reinspe			1 on for this noti	Various locations otice.		
3)	6-108.(a) Violation: Notes:	Exterior 2 2 Living Room Foundations cellars, exterior walls, roofs Repair leaking at roof/wall junction above the bay window causing water seepage into living room an related damage.						
9)	6-109.5.(b) Violation: Notes:	Repair door l	, walls, ceilings,doo atch mechanism for allation of a fire door	safe and		2 ation of egress	Rear Entry door. Remi	nder: Fire Prevention has

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

				4/40/0000			
LARK B		Jeanie Bourke		1/12/2009			
		Status		Inspection Type			
ST	013 B007001			Housing-Housing Inspection			
-116.(e) Interior iolation: Fire Protection		2	2	Living Room			
Replace the battery in the hardwired smoke detector.							
Interior		2	2	Bedroom			
Required equ	uipment and utilitie	es					
Front bedroom - replace baseboard heating tube fins and install protective covers. Repair or replace thermostat.							
Interior		3	3	Kitchen			
Maintenance of lighting fixtures							
Install outlet cover on receptacle behind refridgerator							
Interior		3	3	Living Room			
-							
Install a second duplex outlet near the entertainment center - master electrician required							
Interior		3	3	Bedroom			
Extension cc	ords.						
Remove extension cords and multi outlet strip extending through the doorway to the living room.							
Interior		3	3	Bathroom			
Maintenance of plumbing fixtures.							
Install a code	e compliant cap or	n the plumbing vent f	or washing n	nachine that is not in use.			
Interior		3	3	Entry Way			
Interior floors, walls, ceilings and doors							
Repair damaged wall caused by the entry door knob and install adequate permanent protection.							
Interior		3	3	Kitchen			
Required equipment and utilities							
Repair or replace the gasket on the refridgerator to provide a consistent seal closure around the door.							
) Interior Hallway							
Stairways, stairs, & porches.							
	ST Interior Fire Protection Replace the Interior Required equ Front bedrood thermostat. Interior Maintenance Install outlet of Install a secco Interior Extension co Remove exter Interior Maintenance Install a secco Interior Extension co Remove exter Interior Maintenance Install a code Interior Maintenance Install a code Interior Repair dama Interior Repair or rep Interior	ST CBL 013 B007001 Interior Fire Protection Replace the battery in the hard Interior Interior Required equipment and utilities Front bedroom - replace basel thermostat. Interior Interior Maintenance of lighting fixtures Install outlet cover on receptace Interior Interior Interior Extension cords. Remove extension cords and Interior Maintenance of plumbing fixture Install a code compliant cap o Interior Interior Maintenance of plumbing fixture Install a code compliant cap o Interior Interior Remove extension cords and Interior Interior Maintenance of plumbing fixture Install a code compliant cap o Interior Interior Interior <	CBL 013 B007001 Status Interior 2 Fire Protection 2 Replace the battery in the hardwired smoke detector Interior Interior 2 Required equipment and utilities Front bedroom - replace baseboard heating tube fint thermostat. Interior 3 Maintenance of lighting fixtures Interior Interior 3 Kighting standards/Habitable rooms Interior Interior 3 Extension cords. Remove extension cords and multi outlet strip exter Interior 3 Maintenance of plumbing fixtures. Install a code compliant cap on the plumbing vent finding fixtures. Interior 3 Maintenance of plumbing fixtures. 1 Interior 3 Maintenance of plumbing fixtures. 1 Install a code compliant cap on the plumbing vent finding interior Interior 3 Interior floors, walls, ceilings and doors Repair damaged wall caused by the entry door knoor knoor interior Interior 3 Interior 3 Repair damaged wall caused by the entry door knoo interior	CBL Status Interior 2 2 Fire Protection Replace the battery in the hardwired smoke detector. Interior 2 2 Interior 2 2 2 2 Required equipment and utilities Front bedroom - replace baseboard heating tube fins and install thermostat. 3 3 Interior 3 3 3 Extension cords. Remove extension cords and multi outlet strip extending throug 1 Interior 3 3 3 Interior 3 3 3 Interior 3 3 3 Interior 3			

Comments: