CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date 10/31/2008	
RODRIGUEZ JOSE G &		Jeanie Bourke		
Locatation	CBL	Status	Inspection Type	
32 WASHINGTON AVE	013 E020001	Re-Inspect 30 Days	Complaint-Housing Inspection	

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date			
1)	6-108.b	Interior	2	2	Bathroom				
	Violation:	Interior floors, walls, ceilings and doors							
	Notes:	Floor in the bathroom is in disrepair, finished surface is damaged or removed exposing the subfloor							
2)	6-111.4	Interior	2	2	Bathroom				
	Violation:	n: Maintenance of plumbing fixtures.							
	Notes:	Toilet is not anchored properly and is required to be repaired and maintained as it may be leaking							
3)	6-113.5	Interior	2	2	Kitchen				
	Violation:	Maintenance of lighting fixtures							
	Notes:	Kithchen light has a broken bulb which remains in the socket							
4)	6-113.5	Interior	2	2	Closet				
	Violation:	Maintenance of lighting fixtures							
	Notes:								
5)	6-114.2	Interior	3	2	Living Room				
	Violation:	Heating facilities required.							
	Notes:	There is no central heat supply or code compliant heat source on this floor							
6)	6-116.5	Interior	2	2	Various locati	ons			
	Violation:	Fire Protection							
	Notes:	Battery operated smoke detectors in the kitchen and front bedroom are without batteries.							
7)	6-115.	Interior	2 & 3	2	Hallway				
,	Violation:	Lead-based paint hazard.			·				
	Notes:	Peeling paint and damaged plaster in rear hallway stairs, possible lead hazzard							
8)	6-116.3	Interior	2	2	Hallway				
,	Violation:	Egress Obstructions			,				
	Notes:	Front hallway stair has debris obstructing the	he safe pass	sage for esca	ape				
9)	6-116.2	Interior	3	2	Hallway				
,	Violation:	Egress			,				
	Notes:	•							
	Comments:								

Comments: