## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

March 9, 2017

Responsible Party 1:	Responsible Party 2:		
Cooper Brandon	BRICKLIGHT REALTY		
3250 Sacramento Street	111 COMMERCIAL ST, STE 203		
	PORTLAND, ME 04101		
San Francisco, CA 94115			
Location	CBL	<b>Inspection Date</b>	
<b>Location</b> 7 MONTGOMERY ST	CBL 013 G006001	Inspection Date 2/24/2017	
		- I	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 3/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
<b>1-10.12.1 STREET NUMBERS ON FRONT OF BUILDING</b> ; New and existing buildings shall have approved address numbers placed in a position to be plainly legible and visible from the street or road fronting the property.	//
NFPA 101- 7.5.1.1 AND 7.5.1.1.1 OBSTRUCTED EGRESS; Exits shall be located and exit access shall be arranged so that exits are readily accesible at all times (7.5.1.1). Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4 (7.5.1.1.1).  Overstuffed chair and bicycle on second floor landing	//
NFPA 101- 7.10.9.2 EMERGENCY LIGHTS SHALL BE MAINTAINED; Exit signs connected to, or provided with, a battery-operated emergency illumination source, where required in 7.10.4, shall be tested and maintained in accordance with 7.9.3.  Most of the Emergency lighting didn't function	//
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation.  Label all apartment doors with the appropriate unit number.	//

Violation		Proposed Date of Completion
<b>REQUIRED</b> ; Provide annual fire all be provided by a licensed master frompanies can be found at: <a href="https://www.g.acman.com/www.g.g.">www.g.g.</a>		//
Inspection sticker expired 12/2016		
shall be accessible for operation, in	TEM REQUIRES SERVICE; System valves and gauges aspection, tests, and maintenance.  r wrench are missing from the sprinkler box.	//
FINAL DATE OF COMPLETED V	IOLATION(S)	//
FIRE PREVENTION BUREAU RE	-INSPECTION OF COMPLETED VIOLATION(S)	//
=	reject or modify any proposed plan of action, and may related to complete the proposed plan. Please contact <b>N</b>	_
•	listed within the timeframes provided. If I require addit he Fire Prevention Bureau <u>prior to the deadline</u> to reque iscretion to grant or deny.	
v	y responsibility to schedule a reinspection of my propert y failure to schedule a reinspection shall be deemed an e ed.	•
	ement, I understand that I am liable for penalties pursua $\S$ 1-15 and 10-25, and 30-A M.R.S. $\S$ 4452 and may be so	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	