1121/14/1

THIS IS NOT A BOUNDARY SURVEY

This copyrighted document expires 10-17-14. Reproduction and/or dissemination after this date is unauthorized. MORTGAGE INSPECTION OF: DEED BOOK __3614__ PAGE ___313___ COUNTY __Cumberland DEED BOOK __3959__ PAGE __146__ ADDRESS: 9 & 5 Romasco Lane, Portland, Maine Job Number: ___816-57 Inspection Date: 07-17-14 Scale: 1" = 20'Buyers: 9 Romasco, LLC. Client File #: ___14388 Seller: June Lancaster abutting building 2 story wood house w\ brick foundation 63'± iron fire escape Romasco paved drive abutting building DAVID L. J. HUGHES #2234 abutting building NOTE: Lines of occupation are shown. A boundary survey may yield different results I HEREBY CERTIFY TO: Bay Area Title Services, 9 Romasco, LLC APPARENT EASEMENTS AND RIGHTS OF

and the title insurer.

Monuments found did not conflict with the deed description.

The dwelling setbacks do not violate town zoning requirements.

As delineated on the Federal Emergency Management Agency Community Panel 230051 0014B:

The structure does not fall within the special flood hazard zone. The land does not fall within the special flood hazard zone. A wetlands study has not been performed.

WAY ARE SHOWN. OTHER ENCUMBRANCES, RECORDED OR NOT, MAY EXIST. THIS SKETCH WILL NOT REVEAL ABUTTING DEED CONFLICTS, IF ANY.

Livingston-Hughes

Professional Land Surveyors 88 Guinea Road Kennebunkport, Maine 04046

207-967-9761 phone

207-967-4831 fax

www.livingstonhughes.com