



ENVIRONMENTAL SAFETY & HYGIENE ASSOCIATES, INC.

- Indoor Air Quality
- OSHA Compliance
- Asbestos Consulting
- Training
- Lead Consulting
- Industrial Hygiene

June 23rd, 2015

Mr. Bill Simpson
 Congress 127 Apartments, LLC
 PO Box 6285
 Cape Elizabeth, Maine 04107

Re: Asbestos bulk sampling results for 175 Congress Street, Portland, Maine.

Dear Mr. Simpson:

Environmental Safety & Hygiene Associates, Inc. (ESHA) is providing you with the asbestos bulk testing results for the samples collected from the back deck at 175 Congress Street, Portland, Maine.

As required by the City of Portland, ESHA conducted a visual assessment of a storage shed and back deck system for any suspect asbestos building materials prior to demolition. The assessment was also conducted to assure compliance with the requirements of the MDEP, USEPA National Emission Standard for Hazardous Air Pollutants (NESHAP's).

Based on the visual assessment the shed had no suspect asbestos building materials and the back deck had only suspect rolled roofing that was sampled, tested, and found to be non-asbestos containing (See attached analytical report).


A summary of the building materials sampled and analyzed for asbestos content are as follows;

Material	Location	% Asbestos	Regulated
Rolled Roofing	Back Deck	None Detected	N/A

Based on the findings of this assessment the materials described above do not contain any regulated levels of asbestos.

Should any additional suspect asbestos materials be found during any renovation / demolition, the work should immediately stop until additional sampling can be conducted.

Sincerely,


 Mark Coleman CIE, CMR
 President



P.O. Box 788
Waterville, Maine 04903-0788

999 Forest Avenue
Portland, Maine 04103

ASBESTOS ANALYSIS

Report Date: June 23, 2015

Received Date: 6/22/2015

Administrative Offices
Phone : 207-873-7711
Fax : 207-873-7022

Customer Service
Phone : 207-878-6481
Fax : 207-878-2265

CLIENT

Mark Coleman
Environmental Safety & Hygiene
17 Patrick Drive
Westbrook ME 04092

Analysis Report of Bulk Material via EPA Method 600/R-93/116 Polarized Light Microscopy

SAMPLE ID	Project Number	Project Name	Color	Non-Asbestos		Asbestos
				Fibrous	Non-Fibrous	
RB03446		147 Congress St	Black	03 %	62 %	Not Detected
Client ID/Desc: 1A/Roof		Analyzed Date 6/23/2015	Test: PLM NOB	Analyst ASM/SMD		

Should you have any questions concerning your asbestos test result(s), please feel free to call us. Thank you for using Northeast Laboratory testing services. Contact NEL for your other environmental analytical needs, including water testing for lead and arsenic or indoor air quality.

Authorized by: Bill Sargent, Laboratory Manager

Date: 6/23/2015

Analytical results and reports are generated by NEL at the request of and for the exclusive use of the person or entity (client) named on this report. Results, reports or copies of same will not be released by NEL to any third party without the prior express written consent from the client named in this report. This report applies only to those samples taken at the time, place and location referenced by the client. This report makes no express or implied warranty or guarantee as to the sampling methodology used by the individual performing the sampling. The client is solely responsible for the use and interpretation of these results and NEL makes no express or implied warranties as to such use or interpretation. NEL is not able to make and does not make a determination as to the environmental soundness, safety or health of a property from only the samples sent to their laboratory for analysis. Unless otherwise specified by the Client, NEL reserves the right to dispose of all samples after the testing of such samples is sufficiently completed or after a thirty-day period, whichever period is greater. NEL liability extends only to the cost of the testing. State of Maine license #LB-0082.