CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
HOGLE HEATHER L		Suzanne Hunt	9/28/2009
Locatation	CBL	Status	Inspection Type
82 CUMBERLAND AVE	013 M010001	Re-Inspect 5 Days	Complaint-Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 6-108.(a) Exterior

Violation: Foundations cellars, exterior walls, roofs

Notes: Exterior Doors are broken and not secure. Exterior windows, doors and skylights. Every window or door, including basement or cellar door and hatchway, and skylight shall be substantially weathertight, watertight and vermin proof, and shall be kept secured to prevent ingress of people and animals.

2)

Violation:

Notes:

Comments:

I called Fied Service (sharon) I requested that two exterior door be boarded up and air conditioner removed from sidewalk. She said it would be done by Thursday. Smh DL Property management saidthey were not longer involved with this buildign. Smh Exterior door are not secure, took photo's. smh