Account # - 4R-5705 **NAME I-95 PORTLAND PORTFOLIO**

ZONE#	PASS	FAIL	LOCATION/DESCRIPTION
1	X		BASEMENT PULL STATION BY FACP
2	X		1ST FLOOR REAR PULL STATION
3	X		1ST FLOOR FRONT DOOR PULL STATION
4	X		2ND FLOOR REAR PULL STATION
5	X		2ND FLOOR FRONT PULL STATION
6	X		3RD FLOOR REAR PULL STATION
7	X		3RD FLOOR FRONT PULL STATION
9	X		FACP SMOKE
10	X		1ST FLOOR REAR SMOKE
11	X		1ST FLOOR FRONT SMOKE
12	X		2ND FLOOR REAR SMOKE
13	X		2ND FLOOR FRONT SMOKE
14	X		3RD FLOOR REAR SMOKE
15	X		3RD FLOOR FRONT SMOKE